

AGREED ORDER 2017-0737-IWD-E **Area Totals**

Weight "Pounds"			
EVALUATIONS	FACILITY	COX CREEK	LAVACA BAY
*4/20/19	221.59	0.69	0.06
9/27/2019	46.40	60.40	0.30
3/16/2020	6.91	34.30	0.004
9/17/2020	27.5	27.33	0.005
3/16/2021	0.05	15.5	0.0015
9/16/2021	0.83	26.6	0.002
3/16/2022	0.32	27.9	0.004
9/20/2022	0.56	156.3	0.24
3/29/2023	0.002	512	2.6
9/30/2023	0	575	0.5
3/31/2024	0.8	161	0.8

**04.20.19 evaluation conducted within 60 days based on date issuance of Agreed Order 2017-07-37-IWD-E.*

***For the purpose of calculating amounts for each area 22,000 pellets = 1 lb.*

FACILITY EVALUATION

DESCRIPTION BREAKDOWN (*bags*):

LLDPE: 1 gallon size bag, weight N/A

HDPE-2: 1 gallon size bag, weight N/A

PP-1: 1 gallon size bag, weight 347 grams

PP-2: 1 gallon size bag, weight 1 grams

HDPE-1: 1 gallon size bag, weight 7 grams

OUTFALL 006: 1 gallon size bag, weight N/A

PO-1 SHIPPING: 1 gallon size bags, weight
N/A

OUTFALL 008: 1 gallon size bag, weight N/A

OUTFALL 009: 1 gallon size bag, weight N/A

FACILITY EVALUATION COMMENTS:

The facility evaluations were performed within the facility fence line. 355 grams were found during the facility inspections.

EVALUATION FORM

Facility Evaluation

DATE: 10.3.23

UNIT / AREA: LLDPE

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A

EVALUATION FORM

Facility Evaluation

DATE: 10.4.2023

UNIT / AREA: PP1

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

Plastics were found in both A & B extrusion buildings.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

Operators & THM staff cleaned both areas using vacuums & brooms.

No. of Bags Collected: 2

Estimated Weight of Pellets Recycled: 347 grams

Estimated Weight of Pellets Disposed: N/A

PP1

Extruder building B: Before



Extruder building B: After



PP1

Extruder building A: Before



Extruder building A: After



EVALUATION FORM

Facility Evaluation

DATE: 10.17.2023

UNIT / AREA: HDPE1

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

Plastics were found in within cracks in the concrete near the product & blending silos.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

The THM crew cleaned this area using a vacuum.

No. of Bags Collected: 1

Estimated Weight of Pellets Recycled: 7 grams

Estimated Weight of Pellets Disposed: N/A

PE1

Crack between Product & Blending silos: Before



Crack between Product & Blending silos: After



EVALUATION FORM

Facility Evaluation

DATE: 10.3.2023

UNIT / AREA: PO1 Shipping

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A

EVALUATION FORM

Facility Evaluation

DATE: 11.17.23

UNIT / AREA: PE-2

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A

EVALUATION FORM

Facility Evaluation

DATE: 11.17.2023

UNIT / AREA: PP2

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

Plastics were found on the ground near the silo area

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

The THM crew cleaned this area using vacuums.


No. of Bags Collected: 1

Estimated Weight of Pellets Recycled: 1 gram

Estimated Weight of Pellets Disposed: N/A

PP2

**Outside of blending silo area:
Before**



**Outside of blending silo area:
After**



EVALUATION FORM

Facility Evaluation

DATE: 11.2.23

UNIT / AREA: Outfall 006

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A

EVALUATION FORM

Facility Evaluation

DATE: 11.2.23

UNIT / AREA: Outfall 008

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A

EVALUATION FORM

Facility Evaluation

DATE: 11.2.2023

UNIT / AREA: Outfall 009

DESCRIPTION OF AREAS OBSERVED (*i.e.: 400 area, extrusion, silo storage, OSBL, etc.*)

No plastics were found during this inspection.

ACTIONS TAKEN (Provide response of actions taken to mitigate issue)

N/A

No. of Bags Collected: N/A

Estimated Weight of Pellets Recycled: N/A

Estimated Weight of Pellets Disposed: N/A


Lavaca & Matagorda Bay

Locations include Keller Bay, Cox Bay, shorlines of Lavaca Bay to Port O'Connor.

Legend

 Stops evaluated by Horizon Env.

 Creek





Lavaca & Matagorda Bay


Locations include Keller Bay, Cox Bay, shorelines of Lavaca Bay to Port O'Connor.

Legend

 Stops where pellets were found by Horizon Env.







Interim Cleanup Phases

- Phase 1:** City, County, State (including state submerged lands), Formosa
- Phase 2:** TPWD Foundation, Alcoa, Calhoun County Navigation District
- Phase 3:** All Other Private Landowners (including individuals, estates, corporations)
- Future Re-Assessment**

FORMOSA PLASTIC CORPORATION


Formosa Remediation Consultant

**0.25-Mile Sampling Grids
Interim Cleanup Phases**

FREES NICHOLS
4055 International Plaza, Suite 200
Fort Worth, TX 76109 - 4895
Phone - (817) 735 - 7300

**FIGURE
1-2**

Note: BRAs may include some combination of parcels identified under Phase 1, 2, or 3. BRAs were categorized to the later interim cleanup phase if multiple phases were present.



Lavaca Bay Phase 1: Bay Remediation Areas

During the six month bi-annual report, Horizon Environmental cleaned wracklines in the Phase 1 Bay Remediation Areas (BRA) which are areas along the bay shorelines with the highest possibility of plastic abundance. The BRA locations were provided by remediation consultant Freese & Nichols Inc.

Phase 1 BRA identifies sites presently accessible including properties owned by cities, county, State (including state owned submerged lands), and Formosa Plastics-TX.

There were approximately 18,327 pellets recovered from Lavaca Bay during this evaluation which is approximately 0.8 pounds.

BRA 4 – 0 pellets found within the BRA.

BRA 5 – 0 pellets found within the BRA.

BRA 6 – 0 pellets found within the BRA.

BRA 7 – 0 pellets found within the BRA.

BRA 8 – 0 pellets found within the BRA.

BRA 17 – 0 pellets found within the BRA.

BRA 21 – 0 pellets found within the BRA.

BRA 22 - 0 pellets found within the BRA.

BRA 23 – 0 pellets found within the BRA.

BRA 24 – 0 pellets found within the BRA.

BRA 25 – 0 pellets found within the BRA.

BRA 26 – 0 pellets found within the BRA.

BRA 31 – 0 pellets found within the BRA.

BRA 32 – 0 pellets found within the BRA.

BRA 33 – 0 pellets found within the BRA.

BRA 34– 0 pellets found within the BRA.

BRA 35– 0 pellets found within the BRA.

BRA 61 – 0 pellets found within the BRA.

BRA 62 – 0 pellets found within the BRA.

BRA 74 – 105 pellets found within the BRA.

BRA 81 – 0 pellets found within the BRA.

BRA 83 – 0 pellets found within the BRA.

BRA 84 – 0 pellets found within the BRA.

BRA 85 – 0 pellets found within the BRA.

BRA 86 – 0 pellets found within the BRA.

BRA 90 – 10 pellets found within the BRA.

BRA 91 – 0 pellets found within the BRA.

BRA 92 – 0 pellets found within the BRA.

BRA 117 – 0 pellets found within the BRA.

BRA 118 – 18,212 pellets found within the BRA.


BRA 119 – 0 pellets found within the BRA.

BRA 150 – 0 pellets found within the BRA.

BRA 155 – 0 pellets found within the BRA.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/5/23	BRA #: 90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 8:00am	End Time: 9:00am	Duration: 60min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.583250 -96.608199		
Weather (wind speed/direction, precipitation): 5mph, SSW, 75%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation.		
Most Plastics Collected: YES ☒ NO (if no, explain) ☐		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☒ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: Found 10 pellets.		
Cleanup Technique(s) Implemented¹: 3,5		
No. of Bags Collected: 10		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 10		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA90-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.



Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/4/23	BRA #: 90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 9:00am	End Time: 9:15am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.583334 -96.608216		
Weather (wind speed/direction, precipitation): 0 mph, SSW, 70%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA90-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/4/23	BRA #: BRA90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 9:15 am	End Time: 9:30 am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581608 -96.609440		
Weather (wind speed/direction, precipitation): 5 mph, SSW, 70%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA90-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/4/23	BRA #: 90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 9:30 am	End Time: 9:45 am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581561 -96.609103		
Weather (wind speed/direction, precipitation): 5 mph, SSW, 70%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell Beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA90-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/4/23	BRA #: 90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 9:45 am	End Time: 10:00 am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581454 -96.608812		
Weather (wind speed/direction, precipitation): 5 mph, SSW, 70%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA90-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/4/23	BRA #: 90	Tide: LOW ☐ NORMAL ☐ HIGH ☒
Start Time: 10:00 am	End Time: 10:06 am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581128 -96.606526		
Weather (wind speed/direction, precipitation): 5 mph, SSW, 70%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell Beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA90-6
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 91	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581297 -96.605315		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell hash area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA91-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 91	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581450 -96.604668		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell hash area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA91-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 91	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.581581 -96.604022		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell hash area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA91-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 91	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582092 -96.602763		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA91-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 91	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582449 -96.601531		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA91-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 92	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582960 -96.597079		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA92-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 92	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582892 -96.597365		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA92-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 92	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582796 -96.597657		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA92-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 92	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582541 -96.598207		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA92-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/31/23	BRA #: 92	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.582395 -96.598482		
Weather (wind speed/direction, precipitation): 20mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA92-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/30/23	BRA #: 155	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462217 -96.415923		
Weather (wind speed/direction, precipitation): 20mph, N, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA155-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/30/23	BRA #: 155	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462217 -96.415923		
Weather (wind speed/direction, precipitation): 20mph, N, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA155-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/30/23	BRA #: 155	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462935 -96.415855		
Weather (wind speed/direction, precipitation): 20mph, N, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/30/23	BRA #: 155	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463186 -96.416077		
Weather (wind speed/direction, precipitation): 20mph, N, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 10/30/23	BRA #: 155	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463416 -96.416255		
Weather (wind speed/direction, precipitation): 20mph, N, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA155-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/8/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.536770 -96.514815		
Weather (wind speed/direction, precipitation): 10mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA118-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/8/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.537008 -96.514950		
Weather (wind speed/direction, precipitation): 10mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA118-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/8/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:45am	End Time: 1:00pm	Duration: 4hr 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.537415 -96.515151		
Weather (wind speed/direction, precipitation): 15mph, SSE, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☒ NO (if no, explain) ☐		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☒ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 1	Q2: 0
	Q4: 0	Q5: 4
		Q3: 0
		Q6: 10
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: 3,4,5		
No. of Bags Collected: 29		
Bag Quality Control:	A: 50	B: 32
	D: 75	E: 250
		C: 125
		F: 96
Estimated Number Plastic Pellets Removed²: 18,212		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA118-3 before and after	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.



Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/9/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.538935 -96.515681		
Weather (wind speed/direction, precipitation): 5mph, SE, 5%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA118-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.538935
Longitude: -96.515681
Elevation: 5.55±3.35 m
Accuracy: 4.76 m
Time: 11-09-2023 08:00:05
Note: BRA118-4

GoogleCam 6x 135

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/9/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.539637 -96.515972		
Weather (wind speed/direction, precipitation): 5mph, SE, 5%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA118-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/9/23	BRA #: 118	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.540262 -96.516216		
Weather (wind speed/direction, precipitation): 5mph, SE, 5%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA118-6
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.540262
Longitude: -96.516216
Elevation: 2.93±2.40 m
Accuracy: 9.91 m
Time: 11-09-2023 09:00:08
Note: BRA118-6

NorthCam 60 n05

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.533177 -96.513402		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA119-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.53336 -96.513508		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA119-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.533336
Longitude: -96.513508
Elevation: 3.48±2.40 m
Accuracy: 15.10 m
Time: 11-01-2023 08:30:09
Note: BRA119-2

NoteCam @ iOS

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.534017 -96.513688		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA119-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.534017
Longitude: -96.513688
Elevation: 3.52±2.40 m
Accuracy: 3.71 m
Time: 11-01-2023 09:00:58
Note: BRA119-3

NoteCam © 2.0

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.534279 -96.513818		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA119-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.535518 -96.514348		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA119-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:00am	End Time: 10:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.536061 -96.514559		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA119-6	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/1/23	BRA #: 119	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:30am	End Time: 11:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.536353 -96.514652		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA119-7	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/7/23	BRA #: 150	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.477197 -96.433782		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA150-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/7/23	BRA #: 150	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.477072 -96.433424		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA150-2
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/7/23	BRA #: 150	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.476819 -96.433275		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA150-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/7/23	BRA #: 150	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.476592 -96.433063		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA150-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/7/23	BRA #: 150	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.476424 -96.432789		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA150-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/21/23	BRA #: 74	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:20am	End Time: 9:20am	Duration: 1Hr
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.619924 -96.622088		
Weather (wind speed/direction, precipitation): 15mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☒ NO (if no, explain) ☐		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☒ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: Plastics found and removed from area.		
Cleanup Technique(s) Implemented¹: 5		
No. of Bags Collected: 0		
Bag Quality Control:	A: 60	B: 45
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 105		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA74-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		

a



Shoreline BEFORE interim bay cleanup activities.



Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/21/23	BRA #: 74	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:20am	End Time: 9:50am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.620017 -96.622360		
Weather (wind speed/direction, precipitation): 15mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA74-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/21/23	BRA #: 74	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:50am	End Time: 10:20am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.620188 -96.622620		
Weather (wind speed/direction, precipitation): 15mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA74-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/21/23	BRA #: 74	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:20am	End Time: 10:50am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.618990 -96.622098		
Weather (wind speed/direction, precipitation): 15mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA74-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/21/23	BRA #: 74	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:50am	End Time: 11:20am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.618797 -96.622328		
Weather (wind speed/direction, precipitation): 15mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA74-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.540262 -96.516295		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA117-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.540658 -96.516408		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA117-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.540933 -96.516536		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA117-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.541452 -96.516819		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA117-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.542181 -96.517359		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA117-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 10:00am	End Time: 10:30am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.542900 -96.517901		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA117-6
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 11/15/23	BRA #: 117	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 10:30am	End Time: 11:00am	Duration: 30min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.543158 -96.518073		
Weather (wind speed/direction, precipitation): 5mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA117-7
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 85	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.589506 -96.612081		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA85-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 85	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.588989 -96.611845		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA85-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 85	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.588471 -96.611859		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA85-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 85	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.587826 -96.611996		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA85-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.669581 -96.570816		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 4 -1 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.66.8759 -96.570445		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 4 -1 S	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.669358 -96.571019		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 4 -2 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668577 -96.570746		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 4 -2 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.669239 -96.571239		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 4 -3 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668478 -96.570977		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 4 -3 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 4	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668989 -96.571514		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 4 -4N	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.668989
Longitude: -96.571514
Elevation: 2.13±2.40 m
Accuracy: 2.22 m
Time: 12-26-2023 08:15:03
Note: BRA 4-4 N

Wendy Chen © 2023

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668806 -96.572221		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -1N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668220 -96.571532		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -1S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.668220
Longitude: -96.571532
Elevation: 4.23±3.50 m
Accuracy: 4.64 m
Time: 12-26-2023 07:30:04
Note: BRA 5-1S

NoteCam IP 125

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668784 -96.572544		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -2N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668077 -96.571834		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -2S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668766 -96.572869		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -3N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662571 -96.606128		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 5 -3S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668368 -96.573647		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -4N	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.667398 -96.573245		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -4S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.667305 -96.575487		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -5N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/26/23	BRA #: 5	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666497 -96.574873		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 5 -5S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666886 -96.576078		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 6-1 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666242 -96.575305		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 6 -1 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666617 -96.576660		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 6-2 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.665901 -96.575832		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 6 -2 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666464 -96.576923		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 6-3 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.665414 -96.576595		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 6 -3 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.665276 -96.579001		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 6-4 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664931 -96.576595		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 6 -4 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664322 -96.578335		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 6-5 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.665092
Longitude: -96.579236
Elevation: 2.28±2.40 m
Accuracy: 6.36 m
Time: 12-27-2023 08:30:04
Note: BRA 6-5 N

NotCam 6-105

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 6	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664322 -96.578335		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 6 -5 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.663931 -96.580524		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 7-1 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662741 -96.580202		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7 -1 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.663721 -96.580784		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7-2 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662494 -96.580414		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7 -2 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.663550 -96.581040		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7-3 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662279 -96.580591		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7 -3 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.663356 -96.581290		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7-4 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662050 -96.580785		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 7 -4 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662414 -96.582099		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 7-5 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/27/23	BRA #: 7	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661833 -96.580956		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 7 -5 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592384 -96.611413		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA84-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592188 -96.611572		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA84-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.591941 -96.611729		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA84-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.591941
Longitude: -96.611729
Elevation: 2.45±9.90 m
Accuracy: 5.29 m
Time: 12-12-2023 09:00:10
Note: BRA84-3

NoteCam © 105

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.591359 -96.611822		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA84-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.590446 -96.612105		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA84-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 12/12/23	BRA #: 84	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:00am	End Time: 10:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.589780 -96.612102		
Weather (wind speed/direction, precipitation): 14mph, ESE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA84-6
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.589780
Longitude: -96.612102
Elevation: 2.31±2.40 m
Accuracy: 14.79 m
Time: 12-12-2023 10:30:08
Note: BRA84-6

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 83	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592945 -96.614491		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA83-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 83	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592673 -96.614416		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA83-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 83	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592390 -96.614510		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 83	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.591857 -96.614533		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 83	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.591563 -96.614361		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Date: 1/18/24	BRA #: 86	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:00am	End Time: 10:15am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.590055 -96.613770		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented ¹ : N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed ² : 0		
Estimated Volume Powder Removed ³ : 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA86-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 86	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:15am	End Time: 10:30am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.589969 -96.614077		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA86-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 86	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:30am	End Time: 10:45am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.590122 -96.614668		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA86-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 86	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:45am	End Time: 11:00am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.590284 96.614963		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA86-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/18/24	BRA #: 86	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:00am	End Time: 11:15am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.589992 -96.614958		
Weather (wind speed/direction, precipitation): 15 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA86-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662168 -96.582427		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-1 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661270 -96.581456		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-1 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661966 -96.582663		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-2 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661051 -96.581591		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA8-2 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661773 -96.582913		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-3 N	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.660838 -96.581784		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA8-3 S
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.660838
Longitude: -96.581784
Elevation: 2.85±3.54 m
Accuracy: 4.62 m
Time: 01-02-2024 08:00:42
Note: BRA 8-3 S

NoteCam © iOS

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661574 -96.583189		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA8-4 N
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.660162 -96.582331		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-4 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661359 -96.583383		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-5 N	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/2/24	BRA #: 8	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.659938 -96.582528		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☐ Other (describe below) ☒		
General Site Observations: Asphalt and grass.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8-5 S	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.646377 -96.568375		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA31-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.645813 -96.568357		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA31-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.645277 -96.568467		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA31-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.644961 -96.568592		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA31-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:00am	End Time: 10:30am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.644642 -96.568334		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA31-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 31	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:30am	End Time: 11:00am	Duration: 30mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.644012 -96.568322		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA31-6	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 32	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:00am	End Time: 11:15am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.642659 -96.569125		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA32-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 32	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:15am	End Time: 11:30am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.642399 -96.569339		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA32-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 32	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:30am	End Time: 11:45am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.641857 -96.569531		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA32-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/29/24	BRA #: 32	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:45am	End Time: 12:00pm	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.641409 -96.569558		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA32-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 33	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:15am	End Time: 10:45am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.638707 -96.571683		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA33-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 33	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:45am	End Time: 11:00am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.637536 -96.570237		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA33-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 33	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 11:00am	End Time: 11:15am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.636928 -96.570351		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA33-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 34	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:15am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.642415 -96.572997		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA34-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 34	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:15am	End Time: 9:30am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.641919 -96.572760		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA34-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 34	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 9:45am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.641359 -96.572640		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA34-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24		BRA #: 34	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:45am		End Time: 10:00am	Duration: 15mins
Field Supervisor: Erik			# Crew Members: 5 min
Latitude / Longitude (transect start): 28.640816 -96.572516			
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%			
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐			
General Site Observations: Shell beach			
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.			
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐			
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0			
Qualitative Assessment: No plastics found.			
Cleanup Technique(s) Implemented¹: N/A			
No. of Bags Collected: 0			
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0			
Estimated Number Plastic Pellets Removed²: 0			
Estimated Volume Powder Removed³: 0			
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA34-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 34	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 10:00am	End Time: 10:15am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.640553 -96.572448		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA34-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 35	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.644154 -96.574507		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 35	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.643926 -96.574304		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 35	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.643683 -96.574163		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA35-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 35	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 8:45am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.643261 -96.573889		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/30/24	BRA #: 35	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:45am	End Time: 9:00am	Duration: 15mins
Field Supervisor: Erik		# Crew Members: 5 min
Latitude / Longitude (transect start): 28.643005 -96.573640		
Weather (wind speed/direction, precipitation): 5mph, SSE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell beach		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/17/24	BRA #: 81	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.596724 -96.612535		
Weather (wind speed/direction, precipitation): 10 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA81-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/17/24	BRA #: 81	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.596382 -96.612462		
Weather (wind speed/direction, precipitation): 10 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA81-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/17/24	BRA #: 81	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.596081 -96.612451		
Weather (wind speed/direction, precipitation): 10 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA81-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/17/24	BRA #: 81	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.593232 -96.612663		
Weather (wind speed/direction, precipitation): 10 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA81-4	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 1/17/24	BRA #: 81	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30 min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.593207 -96.612985		
Weather (wind speed/direction, precipitation): 10 mph, S, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA81-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Date: 2/14/24	BRA #: 24	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.631597 -96.562409		
Weather (wind speed/direction, precipitation): 7mph,S,0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented ¹ : N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	F: 0
Estimated Number Plastic Pellets Removed ² : 0		
Estimated Volume Powder Removed ³ : 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA24-1	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/14/24	BRA #: 24	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.632100 -96.562881		
Weather (wind speed/direction, precipitation): 7mph,S,0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA24-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/14/24	BRA #: 24	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.634416 -96.562778		
Weather (wind speed/direction, precipitation): 7mph,S,0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA24-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 25	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 8:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.627693 -96.561625		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA25-1	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 25	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:45am	End Time: 9:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.629149 -96.561759		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA25-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 25	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.629429 -96.561941		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA25-3
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 25	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:15am	End Time: 9:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.629880 -96.562147		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA25-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 25	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 9:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.630253 -96.562193		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA25-5	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Date: 2/13/24	BRA #: 26	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.627454 -96.559416		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented ¹ : N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed ² : 0		
Estimated Volume Powder Removed ³ : 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA26-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 26	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.627204 -96.559532		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA26-2
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 26	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.627004 -96.559833		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA26-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 26	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.626450 -96.560510		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA26-4
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/13/24	BRA #: 26	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.625871 -96.560871		
Weather (wind speed/direction, precipitation): 5mph, SE, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA26-5
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/21/24	BRA #: 17	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.644028 -96.560519		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 17-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/21/24	BRA #: 17	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.645272 -96.558493		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 17-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/21/24	BRA #: 17	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.645506 -96.5576410		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 17-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 21	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:45am	End Time: 9:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.641412 -96.555377		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 21-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 21	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.641428 -96.555059		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 21-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 21	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:15am	End Time: 9:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.641415 -96.554748		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 21-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 22	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:15am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.638772 -96.560924		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 22-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 22	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:15am	End Time: 8:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.638948 -96.560686		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 22-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 22	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 8:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.639107 -96.560424		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 22-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 23	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:15am	End Time: 7:30am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.635233 -96.562705		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 23-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 23	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 7:45am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.600480 -96.578344		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 23-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/20/24	BRA #: 23	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:45am	End Time: 8:00am	Duration: 15 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.638196 -96.561443		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 23-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 61	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:00am	End Time: 7:30am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.648747 -96.623110		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 61-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 61	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 7:30am	End Time: 8:00am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.648794 -96.624580		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 61-2
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 61	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:00am	End Time: 8:30am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.649303 -96.625710		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 61-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 62	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 8:30am	End Time: 9:00am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.649620 -96.626319		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 62-1
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 62	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:00am	End Time: 9:30am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.650241 -96.627976		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 62-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 2/19/24	BRA #: 62	Tide: LOW ☒ NORMAL ☐ HIGH ☐
Start Time: 9:30am	End Time: 10:00am	Duration: 30 mins
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.650836 -96.628955		
Weather (wind speed/direction, precipitation): 5 mph, N, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell beach and vegetation.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment: Q1: 0 Q2: 0 Q3: 0 Q4: 0 Q5: 0 Q6: 0		
Qualitative Assessment: No plastics found.		
Cleanup Technique(s) Implemented¹: N/A		
No. of Bags Collected: 0		
Bag Quality Control: A: 0 B: 0 C: 0 D: 0 E: 0 F: 0		
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA 62-3
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Cox Creek Evaluation Summary

For the evaluation of Cox Creek, locations along the creek shoreline were evaluated. Areas of concern (AOC) were cleaned during this time period and added to this summary. At each stop the immediate area was assessed and, if found, pellets and other debris in the area were removed from Cox Creek during this time period.

There were approximately 3,541,742 pellets recovered from Cox Creek during this evaluation which is approximately 161 pounds.¹

¹ *The source and age of the plastic pellets found has not been determined.*



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Saturday)

DATE: 9/11/2023

AOC 48 START Latitude/Longitude: 28.41.2225479 -96.31.4551526
END: 28.41.2551921 -96.31.4729138

ESTIMATED LF SHORELINE: 366

TOTAL BAGS COLLECTED BY ENTACT: 15 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 11 & 12, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	496	256
2 AOC 48 Shoreline	176	
3 AOC 48 Shoreline	96	

TOTAL ESTIMATED PLASTICS: 3,840



DATE: 9/12/2023

AOC 48 START Latitude/Longitude: 28.41.2225479 -96.31.4551526

END: 28.41.2551921 -96.31.4729138

ESTIMATED LF SHORELINE: 336

TOTAL BAGS COLLECTED BY ENTACT: 15 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 12 & 13, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	120	517.33
2 AOC 48 Shoreline	248	
3 AOC 48 Shoreline	1,184	

TOTAL ESTIMATED PLASTICS: 7,760



DATE: 9/13/2023

AOC 48 START Latitude/Longitude: 28.41.2225479 -96.31.4551526

END: 28.41.2551921 -96.31.4729138

ESTIMATED LF SHORELINE: 336

TOTAL BAGS COLLECTED BY ENTACT: 6 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: September 14, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	512	436
2 AOC 48 Shoreline	360	

TOTAL ESTIMATED PLASTICS: 2,616



DATE: 9/14/2023

AOC 48 START Latitude/Longitude: 28.41.3336919 -96.31.4291720

END: 28.41.3681384 -96.31.4167254

ESTIMATED LF SHORELINE: 378

TOTAL BAGS COLLECTED BY ENTACT: 30 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: September 14, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	256	262.33
2 AOC 48 Shoreline	260	
3 AOC 48 Shoreline	100	
4 AOC 48 Shoreline	352	
5 AOC 48 Shoreline	164	
6 AOC 48 Shoreline	442	

TOTAL ESTIMATED PLASTICS: 7,870



DATE: 9/15/2023

Outfall 09 START Latitude/Longitude: 28.42.0126114 -96.31.4881963

END: 28.42.0063949 -96.31.4920746

ESTIMATED LF SHORELINE: 72

TOTAL BAGS COLLECTED BY ENTACT: 6 at Outfall 09

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: September 15, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 09	1,696	1,420
2 Outfall 09	1,144	

TOTAL ESTIMATED PLASTICS: 8,520



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Saturday)

DATE: 9/18/2023

Outfall 09 START Latitude/Longitude: 28.42.0112478 -96.31.4926624
END: 28.42.0087517 -96.31.4990803

ESTIMATED LF SHORELINE: 62

TOTAL BAGS COLLECTED BY ENTACT: 20 at Outfall 09

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: September 18, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 09	80	144
2 Outfall 09	88	
3 Outfall 09	72	
4 Outfall 09	336	

TOTAL ESTIMATED PLASTICS: 2,880



DATE: 9/19/2023

AOC 48 START Latitude/Longitude: 28.41.2248592 -96.31.4567466

END: 28.41.2517573 -96.31.4718016

ESTIMATED LF SHORELINE: 303

TOTAL BAGS COLLECTED BY ENTACT: 12 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 19, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	640	1,757.33
2 AOC 48 Shoreline	312	
3 AOC 48 Shoreline	4,320	

TOTAL ESTIMATED PLASTICS: 21,088



DATE: 9/20/2023

AOC 48 START Latitude/Longitude: 28.41.2522438 -96.31.4722605

END: 28.41.2812461 -96.31.4696745

ESTIMATED LF SHORELINE: 294

TOTAL BAGS COLLECTED BY ENTACT: 18 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: September 20 & 25, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	248	798
2 AOC 48 Shoreline	104	
3 AOC 48 Shoreline	1,704	
4 AOC 48 Shoreline	1,136	

TOTAL ESTIMATED PLASTICS: 14,364



DATE: 9/21/2023

AOC 48 START Latitude/Longitude: 28.41.2822674 -96.31.4711997

END: 28.41.2931942 -96.31.4628333

ESTIMATED LF SHORELINE: 133

TOTAL BAGS COLLECTED BY ENTACT: 10 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: September 25, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	344	884
2 AOC 48 Shoreline	1,424	

TOTAL ESTIMATED PLASTICS: 8,840



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Saturday)

DATE: 9/25/2023

AOC 48 START Latitude/Longitude: 28.41.2953357 -96.31.4609612

END: 28.41.3145458 -96.31.4407644

ESTIMATED LF SHORELINE: 265

TOTAL BAGS COLLECTED BY ENTACT: 15 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 18, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	784	541.33
2 AOC 48 Shoreline	392	
3 AOC 48 Shoreline	448	

TOTAL ESTIMATED PLASTICS: 8,120.00



DATE: 9/26/2023

AOC 48 START Latitude/Longitude: 28.41.2953357 -96.31.4609612

END: 28.41.3145458 -96.31.4407644

ESTIMATED LF SHORELINE: 265

Outfall 09 START Latitude/Longitude: 28.41.5996650 -96.31.4947349

END: 28.41.5882595 -96.31.5015714

ESTIMATED LF SHORELINE: 130

TOTAL BAGS COLLECTED BY ENTACT: 17 (8 at AOC 48) (9 at Outfall 09)

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 27, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	288	N/A
1 Outfall 09	288	660
2 Outfall 09	1,032	

TOTAL ESTIMATED PLASTICS: 8,244



DATE: 9/27/2023

AOC 48 START Latitude/Longitude: 28.41.3119758 -96.31.4437756

END: 28.41.3260866 -96.31.4338385

ESTIMATED LF SHORELINE: 171

TOTAL BAGS COLLECTED BY ENTACT: 6 at AOC 48

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: September 28, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 48 Shoreline	408	268
2 AOC 48 Shoreline	128	

TOTAL ESTIMATED PLASTICS: 1,608



DATE: 9/28/2023

AOC 04 START Latitude/Longitude: 28.41.5838744 -96.31.5047676

END: 28.41.5527230 -96.31.5389165

ESTIMATED LF SHORELINE: 439

TOTAL BAGS COLLECTED BY ENTACT: 14 at AOC 04

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: September 29, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 04 Shoreline	132	238.67
2 AOC 04 Shoreline	208	
3 AOC 04 Shoreline	376	

TOTAL ESTIMATED PLASTICS: 3,341.33



DATE: 9/29/2023

AOC 04 START Latitude/Longitude: 28.41.5600487 -96.31.5303531

END: 28.41.5387221 -96.31.5459627

ESTIMATED LF SHORELINE: 274

TOTAL BAGS COLLECTED BY ENTACT: 20 at AOC 04

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: September 29, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 04 Shoreline	304	812
2 AOC 04 Shoreline	1,600	
3 AOC 04 Shoreline	440	
4 AOC 04 Shoreline	904	

TOTAL ESTIMATED PLASTICS: 16,240



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Friday)

DATE: 12/11/2023

AOC 08 START Latitude/Longitude: 28.41.4624494 -96.31.4843738

END: 28.41.4210737 -96.31.4350527

ESTIMATED LF SHORELINE: 768

TOTAL BAGS COLLECTED BY ENTACT: 29 at AOC 08

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: December 12, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 08	348	938.67
2 AOC 08	948	
3 AOC 08	1,776	
4 AOC 08	140	
5 AOC 08	968	
6 AOC 08	1,452	

TOTAL ESTIMATED PLASTICS: 27,221.33



DATE: 12/12/2023

Outfall 08 START Latitude/Longitude: 28.41.4886819 -96.31.5115747

END: 28.41.4892630 -96.31.5051967

ESTIMATED LF SHORELINE: 57

AOC 08 START Latitude/Longitude: 28.41.4826585 -96.31.4992603

END: 28.41.4624494 -96.31.4843738

ESTIMATED LF SHORELINE: 244

TOTAL BAGS COLLECTED BY ENTACT: 30 (10 at Outfall 08; 20 at AOC 08)

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: December 13, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 08	896	836
2 Outfall 08	776	
3 AOC 08	1,512	1,776
4 AOC 08	2,384	
5 AOC 08	712	
6 AOC 08	2,496	

TOTAL ESTIMATED PLASTICS: 43,880



DATE: 12/13/2023

Outfall 06 START Latitude/Longitude: 28.41.2059443 -96.31.4476921

END: 28.41.2020229 -96.31.4459400

ESTIMATED LF SHORELINE: 166

TOTAL BAGS COLLECTED BY ENTACT: 8 at AOC 06

TOTAL SAMPLES PROCESSED BY FNI: 2

DATE PROCESSED BY FNI: December 14, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 08	664	564
2 Outfall 08	464	

TOTAL ESTIMATED PLASTICS: 4,512



DATE: 12/14/2023

Outfall 06 START Latitude/Longitude: 28.41.1998102 -96.31.4531868

END: 28.41.2003319 -96.31.4419758

ESTIMATED LF SHORELINE: 120

AOC 08 START Latitude/Longitude: 28.41.4344551 -96.31.4474775

END: 28.41.4393721 -96.31.4554761

ESTIMATED LF SHORELINE: 95

TOTAL BAGS COLLECTED BY ENTACT: 40 (31 at Outfall 06; 9 at AOC 08)

TOTAL SAMPLES PROCESSED BY FNI: 8

DATE PROCESSED BY FNI: December 15, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 06	1,944	1,210.67
2 Outfall 06	84	
3 Outfall 06	3,616	
4 Outfall 06	824	
5 Outfall 06	148	
6 Outfall 06	648	
1 AOC 08	216	508
2 AOC 08	800	

TOTAL ESTIMATED PLASTICS: 42,102.67



DATE: 12/15/2023

AOC 04 START Latitude/Longitude: 28.41.5064065 -96.31.5427360

END: 28.41.5290904 -96.31.5426238

ESTIMATED LF SHORELINE: 232

Outfall 08 START Latitude/Longitude: 28.41.4897558 -96.31.5042080

END: 28.41.4827831 -96.31.4994324

ESTIMATED LF SHORELINE: 57

TOTAL BAGS COLLECTED BY ENTACT: 15 (5 at Outfall 08; 10 at AOC 04)

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: December 18, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 Outfall 08	776	480
2 Outfall 08	184	
1 AOC 04	64	108
2 AOC 04	152	

TOTAL ESTIMATED PLASTICS: 3,480



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Friday)

DATE: 12/18/2023

AOC 04 START Latitude/Longitude: 28.41.5247722 -98.31.5421061

END: 28.41.5510835 -98.31.5402259

ESTIMATED LF SHORELINE: 294

TOTAL BAGS COLLECTED BY ENTACT: 26 at AOC 04

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: December 19, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
1 AOC 04	32	168
2 AOC 04	72	
3 AOC 04	184	
4 AOC 04	64	
5 AOC 04	504	
6 AOC 04	152	

TOTAL ESTIMATED PLASTICS: 4,368



DATE: 12/19/2023

AOC 04 START Latitude/Longitude: 28.41.5517587 -96.31.5404684

END: 28.41.5634627 -96.31.5274827

ESTIMATED LF SHORELINE: 167

AOC 17 START Latitude/Longitude: 28.41.2005014 -96.31.4422586

END: 28.41.2166406 -96.31.4529266

ESTIMATED LF SHORELINE: 192

TOTAL BAGS COLLECTED BY ENTACT: 26 (11 at AOC 04; 15 at AOC 17)

TOTAL SAMPLES PROCESSED BY FNI: 5

DATE PROCESSED BY FNI: December 20, 2023

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at AOC 04	72	144
Bag 2 at AOC 04	216	
Bag 1 at AOC 17	160	261
Bag 2 at AOC 17	408	
Bag 3 at AOC 17	216	

TOTAL ESTIMATED PLASTICS: 5,499



DATE: 12/20/2023

AOC 17 START Latitude/Longitude: 28.41.2005014 -96.31.4422586

END: 28.41.2166406 -96.31.4529266

ESTIMATED LF SHORELINE: 192

TOTAL BAGS COLLECTED BY ENTACT: 30 at AOC 17

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: 12/23/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at AOC 17	25	194
Bag 2 at AOC 17	168	
Bag 3 at AOC 17	24	
Bag 4 at AOC 17	48	
Bag 5 at AOC 17	420	
Bag 6 at AOC 17	480	

TOTAL ESTIMATED PLASTICS: 5,820



DATE: 12/21/2023

Outfall 08 START Latitude/Longitude: 28.41.4913874 -96.31.5409765

END: 28.41.4917854 -96.31.5438472

ESTIMATED LF SHORELINE: GEAR flag #3 -spot cleanup.

TOTAL BAGS COLLECTED BY ENTACT: 6

Outfall 07 START Latitude/Longitude: 28.41.3177102 -96.31.4380722

END: 28.41.3249369 -96.31.4344826

ESTIMATED LF SHORELINE: GEAR flag #5 - spot cleanup.

TOTAL BAGS COLLECTED BY ENTACT: 24

Outfall 06 START Latitude/Longitude: 28.41.1940761 -96.31.4517275

END: 28.42.2002352 -96.31.4548279

ESTIMATED LF SHORELINE: GEAR flag #6 - spot cleanup.

TOTAL BAGS COLLECTED BY ENTACT: 2

TOTAL SAMPLES PROCESSED BY FNI: 8

DATE PROCESSED BY FNI: 12/23/2023.

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Outfall 06, Flag 6 - bag 1	268	268
Outfall 07, Flag 5 – bag 1	1,024	474
Outfall 07, Flag 5 – bag 2	276	
Outfall 07, Flag 5 – bag 3	804	
Outfall 07, Flag 5 – bag 4	220	
Outfall 07, Flag 5 – bag 5	48	
Outfall 08, Flag 3 – bag 1	1,040	1,080
Outfall 08, Flag 3 – bag 2	1,120	

TOTAL ESTIMATED PLASTICS: 18,392



DATE: 12/22/2023

Chance of rain – ENTACT did not surface clean due to bad weather (rain).

ESTIMATED LF SHORELINE: _____

TOTAL BAGS COLLECTED BY ENTACT: __

TOTAL SAMPLES PROCESSED BY FNI: _____

DATE PROCESSED BY FNI: _____

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG

TOTAL ESTIMATED PLASTICS: n/a



Formosa Plastics Surface Cleaning Weekly Summary

(Wednesday – Friday)

DATE: 01/03/2024

AOC 47 NE Turbidity Curtain

AOC 47 SE Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 8 (5 at AOC 47 NE; 3 at AOC 47 SE)

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: January 4, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at AOC 47 NE TBC	840	2,496
Bag 2 at AOC 47 NE TBC	4,152	
Bag 1 at AOC 47 SE TBC	7,584	6,463.5
Bag 2 at AOC 47 SE TBC	5,343	

TOTAL ESTIMATED PLASTICS: 31,870.50



DATE: 01/04/2024

Creek Crossing Curtain North of AOC 40

AOC 47 NE Turbidity Curtain

AOC 47 SE Turbidity Curtain

AOC 17 South Shoreline START Latitude/Longitude: 28.41.1840847 -96.31.4325460

END: 28.41.1874459 -96.31.4323262

ESTIMATED LF SHORELINE: 162

TOTAL BAGS COLLECTED BY ENTACT: 43 (25 at CCC North of AOC 40; 2 at AOC 47 NE TBC; 3 at AOC 47 SE TBC; 13 at AOC 17 South)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: January 5, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at CCC N of AOC 40	32	334.4
Bag 2 at CCC N of AOC 40	112	
Bag 3 at CCC N of AOC 40	48	
Bag 4 at CCC N of AOC 40	56	
Bag 5 at CCC N of AOC 40	1,424	
Bag 1 AOC 47 NE TBC	1,096	1,096
Bag 1 AOC 47 SE TBC	1,288	1,288
Bag 1 AOC 17 South	3,064	2,938.67
Bag 2 AOC 17 South	3,296	
Bag 3 AOC 17 South	2,456	

TOTAL ESTIMATED PLASTICS: 52,618.67



DATE: 01/05/2024

Outfall 08

Outfall 2/4/5 Turbidity Curtain

AOC 47 NE Turbidity Curtain

AOC 47 SE Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 32 (17 at AOC 47 NE TBC; 3 at AOC 47 SE TBC; 6 at Outfall 2,4,5; 6 at Outfall 8)

TOTAL SAMPLES PROCESSED BY FNI: 9

DATE PROCESSED BY FNI: January 8, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at AOC 47 NE TBC	352	480
Bag 2 at AOC 47 NE TBC	432	
Bag 3 at AOC 47 NE TBC	632	
Bag 4 at AOC 47 NE TBC	504	
Bag 1 at AOC 47 SE TBC	4,856	4,856
Bag 1 at Outfall 2/4/5	1,304	1,524
Bag 2 at Outfall 2/4/5	1,744	
Bag 1 at Outfall 08	536	716
Bag 2 at Outfall 08	896	

TOTAL ESTIMATED PLASTICS: 36,168



Formosa Plastics Surface Cleaning Weekly Summary

(Monday – Friday)

DATE: 01/08/2024

AOC 47 SE Turbidity Curtain

Turbidity curtain crossing the creek North of AOC 40

Turbidity curtain crossing the creek SH35

TBC Outfall 08

TBC Outfall 09

TBC Outfall 07

AOC 17 South Shoreline START Latitude/Longitude: 28.41.1840847 -96.31.4325460

END: 28.41.1874459 -96.31.4323262

ESTIMATED LF SHORELINE: 121

TOTAL BAGS COLLECTED BY ENTACT: 59 (23 at AOC 17 South SL; 6 at AOC 47 SE TBC; 10 at TBC CC North of AOC 40; 7 at TBC CC SH35 Turbidity Curtain; 5 at TBC Outfall 09; 3 at TBC Outfall 08; 5 at TBC Outfall 07).

TOTAL SAMPLES PROCESSED BY FNI: 14

DATE PROCESSED BY FNI: January 10, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 AOC 47 SE TBC	9,376	16,560
Bag 2 AOC47 SE TBC	23,744	
Bag 1 TBC CC North of AOC 40	224	332
Bag 2 TBC CC North of AOC 40	440	
Bag 1 TBC CC SH35	304	196
Bag 2 TBC CC SH35	88	
Bag 1 Outfall 08	368	368
Bag 1 Outfall 09	336	336
Bag 1 Outfall 07	3,696	3,696
Bag 1 AOC 17 SL	496	610.4
Bag 2 AOC 17 SL	204	
Bag 3 AOC 17 SL	1,624	
Bag 4 AOC 17 SL	432	
Bag 5 AOC 17 SL	296	

TOTAL ESTIMATED PLASTICS: 139,355.2



DATE: 01/09/2024

TBC AOC 47 SE

TBC Outfall 06

TBC Outfall 08

TBC Outfall 09

GEAR Flag #25 (Outfall 08) START Latitude/Longitude: 28.41.4881929 -96.31.5465446
END: 28.41.4872833 -96.31.5437282

ESTIMATED LF SHORELINE: 27

GEAR Flag #20 (Outfall 08) START Latitude/Longitude: 28.41.4892630 -96.31.5051967
END: 28.41.4886819 -96.31.5115747

ESTIMATED LF SHORELINE: 57

GEAR Flag #15 (Outfall 06) START Latitude/Longitude: 28.41.2009425 -96.31.4450298
END: 28.41.1999700 -96.31.4427943

ESTIMATED LF SHORELINE: 22

GEAR Flag #14 (Outfall 06) START Latitude/Longitude: 28.41.2165077 -96.31.4565226
END: 28.41.2176688 -96.31.4572549

ESTIMATED LF SHORELINE: 13

GEAR Flag #8 (Outfall 06) START Latitude/Longitude: 28.41.2006906 -96.31.4548699
END: 28.41.2013445 -96.31.4552162

ESTIMATED LF SHORELINE: 7

GEAR Flag #4 (Outfall 08) START Latitude/Longitude: 28.41.4892630 -96.31.5051967
END: 28.41.4886819 -96.31.5115747

ESTIMATED LF SHORELINE: 57

GEAR Flag #3 (Outfall 08) START Latitude/Longitude: 28.41.4918136 -96.31.5437198
END: 28.41.4912296 -96.31.5409669

ESTIMATED LF SHORELINE: 25

TOTAL BAGS COLLECTED BY ENTACT: 28 (4 at TBC AOC 47 SE; 4 at Outfall 06; 2 at Outfall 08; 2 at Outfall 09; 4 at GEAR Flag #25; 3 at GEAR Flag #20; 1 at GEAR Flag #15; 1 at GEAR Flag #14; 2 at GEAR Flag #8; 2 at GEAR Flag #4; 3 at GEAR Flag #3)

TOTAL SAMPLES PROCESSED BY FNI: 11

DATE PROCESSED BY FNI: January 11, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at TBC 47 SE	15,408	15,408
Bag 1 at Outfall 06	848	848
Bag 1 at Outfall 08	672	672
Bag 1 at Outfall 09	336	336
Bag 1 at GEAR Flag #3 (Outfall 08)	328	328
Bag 1 at GEAR Flag #4 (Outfall 08)	452	452
Bag 1 at GEAR Flag #8 (Outfall 06)	224	224
Bag 1 at GEAR Flag #14 (Outfall 06)	176	176
Bag 1 at GEAR Flag #15 (Outfall 06)	624	624
Bag 1 at GEAR Flag #20 (Outfall 08)	664	664
Bag 1 at GEAR Flag #25 (Outfall 08)	408	408

TOTAL ESTIMATED PLASTICS: 73,800



DATE: 01/10/2024

GEAR Flag #26 (Outfall 09) START Latitude/Longitude: 28.42.0082497 -96.31.5160658
END: 28.42.0097286 -96.31.5105580

ESTIMATED LF SHORELINE: 51

GEAR Flag #21 (Outfall 09) START Latitude/Longitude: 28.41.5853273 -96.31.5047783
END: 28.41.5884453 -96.31.5044169

ESTIMATED LF SHORELINE: 32

GEAR Flag #3 (Outfall 08) START Latitude/Longitude: 28.41.4918136 -96.31.5437198
END: 28.41.4912296 -96.31.5409669

ESTIMATED LF SHORELINE: 25

TOTAL BAGS COLLECTED BY ENTACT: 23 (18 at GEAR Flag #3; 3 at GEAR Flag #21; 2 at GEAR Flag #26).

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: January 12, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at GEAR Flag #3 (Outfall 09)	408	336
Bag 2 at GEAR Flag #3 (Outfall 09)	456	
Bag 3 at GEAR Flag #3 (Outfall 09)	192	
Bag 4 at GEAR Flag #3 (Outfall 09)	288	
Bag 1 at GEAR Flag #21 (Outfall 09)	432	432
Bag 1 at GEAR Flag #26 (Outfall 08)	920	920

TOTAL ESTIMATED PLASTICS: 9,184



DATE: 01/11/2024

TBC AOC 47 SE

CC North of AOC 1

TBC West of Outfall 12

GEAR Flag #26 (Outfall 09) START Latitude/Longitude: 28.42.0082497 -96.31.5160658
END: 28.42.0097286 -96.31.5105580

ESTIMATED LF SHORELINE: 51

GEAR Flag #1 (Outfall 09) START Latitude/Longitude: 28.42.0039547 -96.31.5565438
END: 28.42.0019524 -96.31.5567432

ESTIMATED LF SHORELINE: 20

AOC 40 SL START Latitude/Longitude: 28.42.0869508 -96.31.4653385
END: 28.42.0732518 -96.31.4592526

ESTIMATED LF SHORELINE: 150

TOTAL BAGS COLLECTED BY ENTACT: 7 (2 at GEAR Flag #1; 1 at GEAR Flag #26; 1 at TBC AOC 47 SE; 1 at AOC 40 SL; 1 at CC North of AOC 1; 1 at TBC West of Outfall 12).

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: January 12, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at GEAR Flag #1 (Outfall 09)	128	128
Bag 1 at GEAR Flag #26 (Outfall 09)	736	736
Bag 1 at TBC AOC 47 SE	4,288	4,288
Bag 1 at AOC 40 SL	208	208
Bag 1 at GCC North of AOC 1	96	96
Bag 1 at TBC West of Outfall 12	176	176

TOTAL ESTIMATED PLASTICS: 5,760



DATE: 01/12/2024

AOC 40 SL START Latitude/Longitude: 28.42.0702863 -96.31.4591356
END: 28.42.0602601 -96.31.4692838

ESTIMATED LF SHORELINE: 184

TOTAL BAGS COLLECTED BY ENTACT: 1 bag at AOC 40 Shoreline

TOTAL SAMPLES PROCESSED BY FNI: 1

DATE PROCESSED BY FNI: January 12, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 at AOC 40 SL	196	196

TOTAL ESTIMATED PLASTICS: 196



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 1/15/2024

LOCATION: AOC 40 SL

START Latitude/Longitude: 28.42.0099815, -96.31.5066937

END Latitude/Longitude: 28.42.0197332, -96.31.4883208

ESTIMATED LF SHORELINE: 205

TOTAL BAGS COLLECTED BY ENTACT: 5 at AOC 40 shoreline

TOTAL SAMPLES PROCESSED BY FNI: 3

DATE PROCESSED BY FNI: 1/16/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 40	16	581.33
Bag 2 AOC 40	72	
Bag 3 AOC 40	1,656	

TOTAL ESTIMATED PLASTICS: 2,906.67



DATE: 1/16/2024

LOCATION: AOC 04

START Latitude/Longitude: 28.41.5777981, -96.31.5096753

END Latitude/Longitude: 28.41.5724233, -96.31.5163108

ESTIMATED LF SHORELINE: 80

TOTAL BAGS COLLECTED BY ENTACT: 48 BAGS AT AOC 04

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 1/17/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 04	264	180.8
Bag 2 AOC 04	136	
Bag 3 AOC 04	184	
Bag 4 AOC 04	120	
Bag 5 AOC 04	360	
Bag 6 AOC 04	168	
Bag 7 AOC 04	80	
Bag 8 AOC 04	152	
Bag 9 AOC 04	88	
Bag 10 AOC 04	256	

TOTAL ESTIMATED PLASTICS: 8,678.4



DATE: 1/17/2024

LOCATION:

AOC 04

START Latitude/Longitude: 28.41.5777981, -96.31.5096753

END Latitude/Longitude: 28.41.5724233, -96.31.5163108

ESTIMATED LF SHORELINE: 80

GEAR Flag #2 (Outfall 09)

START Latitude/Longitude: 28.42.0070627, -96.31.5237227

END Latitude/Longitude: 28.42.0080457, -96.31.5224408

ESTIMATED LF SHORELINE: 15

GEAR Flag #27 (Outfall 08)

START Latitude/Longitude: 28.41.4836255, -96.31.5213709

END Latitude/Longitude: 28.41.4836145, -96.31.5202405

ESTIMATED LF SHORELINE: 10

GEAR Flag #28 (Outfall 07)

START Latitude/Longitude: 28.41.3268023, -96.31.4338437

END Latitude/Longitude: 28.41.3293061, -96.31.4333443

ESTIMATED LF SHORELINE: 26

GEAR Flag #29 (Outfall 08)

START Latitude/Longitude: 28.41.4967709, -96.31.5372584

END Latitude/Longitude: 28.41.4960904, -96.31.5333140

ESTIMATED LF SHORELINE: 36

GEAR Flag #30 (Outfall 07)

START Latitude/Longitude: 28.41.3228625, -96.31.4356468

END Latitude/Longitude: 28.41.3221249, -96.31.4358542

ESTIMATED LF SHORELINE: 8

TOTAL BAGS COLLECTED BY ENTACT: 59 (50 at AOC 04, 1 at GEAR Flag #2, 1 at GEAR Flag #27, 2 at GEAR Flag #28, 3 at GEAR Flag #29, 2 at GEAR Flag #30)

TOTAL SAMPLES PROCESSED BY FNI: 15 (10 at AOC 04, 1 at GEAR flag #2, 1 at GEAR flag #27, 1 at GEAR flag #28, 1 at GEAR flag #29, 1 at GEAR flag #30)

DATE PROCESSED BY FNI: 1/18/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 04	104	227.2
Bag 2 AOC 04	120	
Bag 3 AOC 04	440	
Bag 4 AOC 04	216	
Bag 5 AOC 04	56	
Bag 6 AOC 04	160	
Bag 7 AOC 04	328	
Bag 8 AOC 04	360	
Bag 9 AOC 04	280	
Bag 10 AOC 04	208	
Bag 1 at GEAR Flag #2 (Outfall 09)	192	192
Bag 1 at GEAR Flag #27 (Outfall 08)	434	434
Bag 1 at GEAR Flag #28 (Outfall 07)	304	304
Bag 1 at GEAR Flag #29 (Outfall 08)	168	168
Bag 1 at GEAR Flag #30 (Outfall 07)	24	24

TOTAL ESTIMATED PLASTICS: 13,146



DATE: 1/18/2024

LOCATION: AOC 04

START Latitude/Longitude: 28.41.5720910, -96.31.5167418

END Latitude/Longitude: 28.41.5659019, -96.31.5249877

ESTIMATED LF SHORELINE: 96

TOTAL BAGS COLLECTED BY ENTACT: 47 bags at AOC 04

TOTAL SAMPLES PROCESSED BY FNI: 10 at AOC 04

DATE PROCESSED BY FNI: 1/19/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
1 AOC 04	424	325.6
2 AOC 04	488	
3 AOC 04	504	
4 AOC 04	248	
5 AOC 04	208	
6 AOC 04	368	
7 AOC 04	304	
8 AOC 04	184	
9 AOC 04	208	
10 AOC 04	320	

TOTAL ESTIMATED PLASTICS: 15,303.2



DATE: 1/19/2024

LOCATION: AOC 04

START Latitude/Longitude: 28.41.5720910, -96.31.5167418

END Latitude/Longitude: 28.41.5659019, -96.31.5249877

ESTIMATED LF SHORELINE: 96

TOTAL BAGS COLLECTED BY ENTACT: 49 (5 at AOC 47 SE turbidity curtain, 1 at AOC 47 NE turbidity curtain, 43 at AOC 04)

TOTAL SAMPLES PROCESSED BY FNI: 11 (1 At AOC 47 SE turbidity curtain, 1 at AOC 47 NE turbidity curtain, 9 at AOC 04)

DATE PROCESSED BY FNI: January 19, 2024; January 24 & January 25, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
1 AOC 47 NE turbidity curtain	5,200	9,400
1 AOC 47 SE turbidity curtain	13,600	
1 AOC 04	1,072	937.78
2 AOC 04	392	
3 AOC 04	1,200	
4 AOC 04	1,216	
5 AOC 04	400	
6 AOC 04	608	
7 AOC 04	1,168	
8 AOC 04	1,568	
9 AOC 04	816	

TOTAL ESTIMATED PLASTICS: 96,724.44



Formosa Plastics Surface Cleaning Weekly Summary

(Wednesday – Friday)

DATE: 01/24/2024

No surface cleaning activities due to heavy rain.

TOTAL BAGS COLLECTED BY ENTACT: N/A

TOTAL SAMPLES PROCESSED BY FNI: N/A

DATE PROCESSED BY FNI: N/A

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
N/A	N/A	N/A

TOTAL ESTIMATED PLASTICS: N/A



DATE: 01/25/2024

Outfall 02/04/05 Turbidity Curtain

AOC 47 SE Turbidity Curtain

Boat Launch Pad

TOTAL BAGS COLLECTED BY ENTACT: 25 (5 at Outfall 02/04/05; 10 at AOC 47 SE TBC; 10 at Boat Launch Pad)

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: January 26, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 Outfall 02/04/05	2,032	1,984
Bag 2 Outfall 02/04/05	1,936	
Bag 1 AOC 47 SE	11,984	17,288
Bag 2 AOC 47 SE	22,592	
Bag 1 Boat Launch Pad	3,656	5,152
Bag 2 Boat Launch Pad	6,648	

TOTAL ESTIMATED PLASTICS: 234,320



DATE: 01/26/2024

AOC 47 SE Turbidity Curtain

LOCATION: AOC 20

START Latitude/ Longitude: 28.41.1806863, -96.31.4292982

END Latitude/ Longitude: 28.41.1769332, -96.31.4243674

ESTIMATED LF SHORELINE: 58

TOTAL BAGS COLLECTED BY ENTACT: 33 (22 at AOC 47 SE TBC; 11 at AOC 20)

TOTAL SAMPLES PROCESSED BY FNI: 7

DATE PROCESSED BY FNI: January 29, 2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER PLASTICS PER BAG
Bag 1 AOC 47 SE TBC	19,200	16,160
Bag 2 AOC 47 SE TBC	13,120	
Bag 1 AOC 20	216	689.6
Bag 2 AOC 20	904	
Bag 3 AOC 20	816	
Bag 4 AOC 20	128	
Bag 5 AOC 20	1,384	

TOTAL ESTIMATED PLASTICS: 363,105.6



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 1/29/2024

LOCATION: AOC 20

START Latitude/Longitude: 28.41.1806863, -96.31.4292982

END Latitude/Longitude: 28.41.1769332, -96.31.4243674

ESTIMATED LF SHORELINE: 58

LOCATION: GEAR Flag #31 (Outfall 08)

START Latitude/Longitude: 28.41.4842597, -96.31.5292891

END Latitude/Longitude: 28.41.4841655, -96.31.5275768

ESTIMATED LF SHORELINE: 15

LOCATION: GEAR Flag #32 (Outfall 06)

START Latitude/Longitude: 28.41.1997078, -96.31.4331191

END Latitude/Longitude: 28.41.2000591, -96.31.4426107

ESTIMATED LF SHORELINE: 6

LOCATION: GEAR Flag #33 (Outfall 09)

START Latitude/Longitude: 28.42.0020952, -96.31.5565601

END Latitude/Longitude: 28.42.0040983, -96.31.5565023

ESTIMATED LF SHORELINE: 33

AOC 47 SE Turbidity Curtain

AOC 47 NE Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 50 (18 at AOC 47 SE turbidity curtain; 7 at AOC 47 NE turbidity curtain; 1 at GEAR flag #31 (Outfall 08); 4 at GEAR flag #32 (Outfall 06); 1 at GEAR flag #33 (Outfall 09); 19 at AOC 20)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 1/30/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 47 SE turbidity curtain	26,112	30,476
Bag 2 AOC 47 SE turbidity curtain	52,800	
Bag 3 AOC 47 SE turbidity curtain	13,392	
Bag 4 AOC 47 SE turbidity curtain	29,600	
Bag 1 AOC 47 NE turbidity curtain	7,040	5,976
Bag 2 AOC 47 NE turbidity curtain	4,912	
Bag 1 at GEAR Flag #31 (Outfall 08)	2,136	2,136
Bag 1 at GEAR Flag #32 (Outfall 06)	448	448
Bag 1 at GEAR Flag #33 (Outfall 09)	584	584
Bag 1 AOC 20	1,992	1,364
Bag 2 AOC 20	136	
Bag 3 AOC 20	2,112	
Bag 4 AOC 20	1,216	

TOTAL ESTIMATED PLASTICS: 620,828



DATE: 1/30/2024

LOCATION: AOC 20

START Latitude/Longitude: 28.41.1668170, -96.31.4116368

END Latitude/Longitude: 28.41.1512477, -96.31.4041077

ESTIMATED LF SHORELINE: 171

LOCATION: AOC 21

START Latitude/Longitude: 28.41.1022207, -96.31.4226458

END Latitude/Longitude: 28.41.1066019, -96.31.4178935

ESTIMATED LF SHORELINE: 61

LOCATION: AOC 38

START Latitude/Longitude: 28.40.5431883, -96.32.0933829

END Latitude/Longitude: 28.40.5447146, -96.32.1048082

ESTIMATED LF SHORELINE: 107

LOCATION: AOC 43

START Latitude/Longitude: 28.40.550784, -96.32.1181555

END Latitude/Longitude: 28.40.5606289, -96.32.1168909

ESTIMATED LF SHORELINE: 103

AOC 47 NE Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 69 (9 at AOC 47 NE turbidity curtain; 12 at AOC 20; 16 at AOC 21; 25 at AOC 38; 7 at AOC 43)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 1/31/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 47 NE turbidity curtain	13,888	16,944
Bag 2 AOC 47 NE turbidity curtain	20,000	
Bag 1 at AOC 20	3,024	3,208
Bag 2 at AOC 20	3,392	
Bag 1 at AOC 21	824	1,368
Bag 2 at AOC 21	1,072	
Bag 3 at AOC 21	2,208	
Bag 1 at AOC 38	216	739.2
Bag 2 at AOC 38	1,104	
Bag 3 at AOC 38	920	
Bag 4 at AOC 38	320	
Bag 5 at AOC 38	1,136	
Bag 1 at AOC 43	128	128

TOTAL ESTIMATED PLASTICS: 232,256



DATE: 1/31/2024

LOCATION: AOC 24

START Latitude/Longitude: 28.40.5357257, -96.32.0828280

END Latitude/Longitude: 28.40.4952658, -96.32.0739720

ESTIMATED LF SHORELINE: 457

LOCATION: AOC 38

START Latitude/Longitude: 28.40.5431883, -96.32.0933829

END Latitude/Longitude: 28.40.544146, -96.32.1048082

ESTIMATED LF SHORELINE: 107

TOTAL BAGS COLLECTED BY ENTACT: 31 (25 at AOC 24; 6 at AOC 38)

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: 2/1/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 at AOC 24	608	1,452.8
Bag 2 at AOC 24	4,160	
Bag 3 at AOC 24	544	
Bag 4 at AOC 24	768	
Bag 5 at AOC 24	1,184	
Bag 1 at AOC 38	2,174	2,174

TOTAL ESTIMATED PLASTICS: 49,364



DATE: 2/1/2024

LOCATION: AOC 25

START Latitude/Longitude: 28.40.4427475, -96.32.1014565

END Latitude/Longitude: 28.40.3903987, -96.32.0824940

ESTIMATED LF SHORELINE: 271

LOCATION: AOC 27

START Latitude/Longitude: 28.40.3289497, -96.32.0214377

END Latitude/Longitude: 28.40.3260205, -96.32.0174027

ESTIMATED LF SHORELINE: 47

LOCATION: AOC 44

START Latitude/Longitude: 28.40.3782914, -96.32.0759486

END Latitude/Longitude: 28.40.3698165, -96.32.0733152

ESTIMATED LF SHORELINE: 89

LOCATION: AOC 45

START Latitude/Longitude: 28.40.3364946, -96.32.0398146

END Latitude/Longitude: 28.40.3322445, -96.32.0294649

ESTIMATED LF SHORELINE: 102

TOTAL BAGS COLLECTED BY ENTACT: 57 (50 at AOC 25; 5 at AOC 27; 1 at AOC 44; 1 at AOC 45)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 1/2/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 at AOC 25	108	1,109.2
Bag 2 at AOC 25	3,520	
Bag 3 at AOC 25	608	
Bag 4 at AOC 25	992	
Bag 5 at AOC 25	96	
Bag 6 at AOC 25	24	
Bag 7 at AOC 25	1,680	
Bag 8 at AOC 25	2,208	
Bag 9 at AOC 25	1,136	
Bag 10 at AOC 25	720	
Bag 1 at AOC 27	2,304	2,304
Bag 1 at AOC 44	2,768	2,768
Bag 1 at AOC 45	0	0

TOTAL ESTIMATED PLASTICS: 69,748



DATE: 2/2/2024

LOCATION: AOC 27

START Latitude/Longitude: 28.40.3289497, -96.32.0214377

END Latitude/Longitude: 28.40.3260205, -96.32.0174027

ESTIMATED LF SHORELINE: 47

LOCATION: AOC 28

START Latitude/Longitude: 28.40.3129126, -96.31.5898595

END Latitude/Longitude: 28.40.2992439, 096.31.5862148

ESTIMATED LF SHORELINE: 142

LOCATION: AOC 29

START Latitude/Longitude: 28.40.2538305, -96.31.5330488

END Latitude/Longitude: 28.40.2658698, -96.31.5365648

ESTIMATED LF SHORELINE: 126

TOTAL BAGS COLLECTED BY ENTACT: 56 (5 at AOC 27; 42 at AOC 28; 9 at AOC 29)

TOTAL SAMPLES PROCESSED BY FNI: 11

DATE PROCESSED BY FNI: 2/5/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 at AOC 27	8,592	8,592
Bag 1 at AOC 28	80	44
Bag 2 at AOC 28	0	
Bag 3 at AOC 28	224	
Bag 4 at AOC 28	16	
Bag 5 at AOC 28	0	
Bag 6 at AOC 28	16	
Bag 7 at AOC 28	16	
Bag 8 at AOC 28	0	
Bag 1 at AOC 29	496	3,672
Bag 2 at AOC 29	6,848	

TOTAL ESTIMATED PLASTICS: 77,856



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 2/5/2024

LOCATION: AOC 29

START Latitude/Longitude: 28.40.1735498, -96.31.5196707

END Latitude/Longitude: 28.40.1604772, -96.31.5261155

ESTIMATED LF SHORELINE: 144

LOCATION: AOC 46

START Latitude/Longitude: 28.40.1014424, -96.31.5662227

END Latitude/Longitude: 28.40.0907035, -96.31.5736829

ESTIMATED LF SHORELINE: 127

LOCATION: AOC 30

START Latitude/Longitude: 28.40.0663753, -96.31.5930526

END Latitude/Longitude: 28.40.0606879, -96.32.0012047

ESTIMATED LF SHORELINE: 93

TOTAL BAGS COLLECTED BY ENTACT: 43 (17 at AOC 29; 22 at AOC 46; 4 at AOC 30)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/6/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 29	16	8
Bag 2 AOC 29	0	
Bag 3 AOC 29	8	
Bag 4 AOC 29	8	
Bag 1 AOC 46	48	33.6
Bag 2 AOC 46	16	
Bag 3 AOC 46	64	
Bag 4 AOC 46	40	
Bag 5 AOC 46	0	
Bag 1 AOC 30	0	0

TOTAL ESTIMATED PLASTICS: 875.2



DATE: 2/6/2024

Location: GEAR Flag #34 (Outfall 09)

START Latitude/Longitude: 28.42.0050725, -96.31.5199420

END Latitude/Longitude: 28.42.0064994, -96.31.5192384

ESTIMATED LF SHORELINE: 16

Location: GEAR Flag #35 (Outfall 09)

START Latitude/Longitude: 28.42.0030882, -96.31.5566713

END Latitude/Longitude: 28.42.0014853, -96.31.5568603

ESTIMATED LF SHORELINE: 16

Location: GEAR Flag #36 (Outfall 08)

START Latitude/Longitude: 28.41.4880502, -96.31.5464038

END Latitude/Longitude: 28.41.4874060, -96.31.5437798

ESTIMATED LF SHORELINE: 24

Location: GEAR Flag #37 (Outfall 08)

START Latitude/Longitude: 28.41.4882098, -96.31.5132991

END Latitude/Longitude: 28.41.4892425, -96.31.5113184

ESTIMATED LF SHORELINE: 29

Location: GEAR Flag #38 (Outfall 06)

START Latitude/Longitude: 28.41.2170000, -96.31.4536249

END Latitude/Longitude: 28.41.2153104, -96.31.4526815

ESTIMATED LF SHORELINE: 19

Location: GEAR Flag #39 (Outfall 06)

START Latitude/Longitude: 28.41.2018588, -96.31.4442408

END Latitude/Longitude: 28.41.2021730, -96.31.4453874

ESTIMATED LF SHORELINE: 11

Location: GEAR Flag #40 (Outfall 06)

START Latitude/Longitude: 28.41.2008746, -96.31.4548551

END Latitude/Longitude: 28.41.1998343, -96.31.4525217

ESTIMATED LF SHORELINE: 30



Location: GEAR Flag #41 (Outfall 08)

START Latitude/Longitude: 28.41.4905430, -96.31.5040434

END Latitude/Longitude: 28.41.4923409, -96.31.5035825

ESTIMATED LF SHORELINE: 19

Location: GEAR Flag #42 (Outfall 09)

START Latitude/Longitude: 28.42.0031706, -96.31.5115934

END Latitude/Longitude: 28.42.0021001, -96.31.5103781

ESTIMATED LF SHORELINE: 15

Location: GEAR Flag #43 (Outfall 08)

START Latitude/Longitude: 28.41.4910865, -96.31.5413120

END Latitude/Longitude: 28.41.4917392, -96.31.5445163

ESTIMATED LF SHORELINE: 29

TOTAL BAGS COLLECTED BY ENTACT: 25 (1 at GEAR Flag #34; 1 at GEAR Flag #35; 1 at GEAR Flag 36; 1 at GEAR Flag #37; 2 at GEAR Flag #38; 2 at GEAR Flag #39; 5 at GEAR Flag #40; 1 at GEAR Flag #41; 1 at GEAR Flag #42; 10 at GEAR Flag #43)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/7/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 GEAR Flag #34 (Outfall 09)	88	88
Bag 1 GEAR Flag #35 (Outfall 09)	648	648
Bag 1 GEAR Flag #36 (Outfall 08)	672	672
Bag 1 GEAR Flag #37 (Outfall 08)	808	808
Bag 1 GEAR Flag #38 (Outfall 06)	1,496	1,496
Bag 1 GEAR Flag #39 (Outfall 06)	4,544	4,544
Bag 1 GEAR Flag #40 (Outfall 06)	3,096	3,096
Bag 1 GEAR Flag #41 (Outfall 08)	288	288
Bag 1 GEAR Flag #42 (Outfall 09)	408	408
Bag 1 GEAR Flag #43 (Outfall 08)	120	424
Bag 2 GEAR Flag #43 (Outfall 08)	728	

TOTAL ESTIMATED PLASTICS: 34,712



DATE: 2/7/2024

Location: GEAR Flag #43 (Outfall 08)

START Latitude/Longitude: 28.42.0017750, -96.31.5561987

END Latitude/Longitude: 28.42.0036464, -96.31.5559520

ESTIMATED LF SHORELINE: 29

Location: AOC 4

START Latitude/Longitude: 28.41.4976123, -96.31.5445788

END Latitude/Longitude: 28.41.4967551, -96.31.5409538

ESTIMATED LF SHORELINE: 33

Location: Outfall 02/04/05

START Latitude/Longitude: 28.41.0426142, -96.32.1216684

END Latitude/Longitude: 28.41.0354174, -96.32.1193298

ESTIMATED LF SHORELINE: 76

TOTAL BAGS COLLECTED BY ENTACT: 15 (8 at GEAR Flag #43; 5 at AOC 4; 2 at Outfall 02/04/05)

TOTAL SAMPLES PROCESSED BY FNI: 4

DATE PROCESSED BY FNI: 2/8/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 GEAR Flag #43 (Outfall 08)	824	720
Bag 2 GEAR Flag #43 (Outfall 08)	616	
Bag 1 AOC 4	1,976	1,976
Bag 1 Outfall 02/04/05	112	112

TOTAL ESTIMATED PLASTICS: 15,864



DATE: 2/8/2024

Location: GEAR Flag #44 (Outfall 09)

START Latitude/Longitude: 28.42.0017750, -96.31.5561987

END Latitude/Longitude: 28.42.0036464, -96.31.5559520

ESTIMATED LF SHORELINE: 19

Location: AOC 4

START Latitude/Longitude: 28.41.4976123, -96.31.5445788

END Latitude/Longitude: 28.41.4967551, -96.31.5409538

ESTIMATED LF SHORELINE: 33

Location: Outfall 08

START Latitude/Longitude: 28.41.4821588, -96.31.5004200

END Latitude/Longitude: 28.41.4834455, -96.31.5106281

ESTIMATED LF SHORELINE: 92

Location: Outfall 06

START Latitude/Longitude: 28.41.2051259, -96.31.4487440

END Latitude/Longitude: 28.41.2024646, -96.31.4540792

ESTIMATED LF SHORELINE: 55

Location: Outfall 02/04/05

START Latitude/Longitude: 28.41.0426142, -96.32.1216684

END Latitude/Longitude: 28.41.0354174, -96.32.1193298

ESTIMATED LF SHORELINE: 76

Location: AOC 20

START Latitude/Longitude: 28.41.1827708, -96.31.4309774

END Latitude/Longitude: 28.41.1731972, -96.31.4197344

ESTIMATED LF SHORELINE: 139

TOTAL BAGS COLLECTED BY ENTACT: 56 (1 at GEAR Flag #44; 14 at AOC 4; 15 at Outfall 08; 9 at Outfall 06; 7 at Outfall 02/04/05; 10 at AOC 20)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 2/8/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 GEAR Flag #44 (Outfall 09)	1,504	1,504
Bag 1 AOC 4	3,232	2,912
Bag 2 AOC 4	1,936	
Bag 3 AOC 4	3,568	
Bag 1 Outfall 08	2,704	2,778.67
Bag 2 Outfall 08	3,008	
Bag 3 Outfall 08	2,624	
Bag 1 Outfall 06	848	2,048
Bag 2 Outfall 06	3,248	
Bag 1 Outfall 02/04/05	2,918	3,115
Bag 2 Outfall 02/04/05	3,312	
Bag 1 AOC 20	15,968	12,992
Bag 2 AOC 20	10,016	

TOTAL ESTIMATED PLASTICS: 254,109



DATE: 2/9/2024

Location: Outfall 02/04/05

START Latitude/Longitude: 28.41.0346303, -96.32.1232613

END Latitude/Longitude: 28.41.0290866, -96.32.1153446

ESTIMATED LF SHORELINE: 242

TOTAL BAGS COLLECTED BY ENTACT: 31

TOTAL SAMPLES PROCESSED BY FNI: 7

DATE PROCESSED BY FNI: 2/12/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 Outfall 02/04/05	104	672.86
Bag 2 Outfall 02/04/05	512	
Bag 3 Outfall 02/04/05	696	
Bag 4 Outfall 02/04/05	168	
Bag 5 Outfall 02/04/05	928	
Bag 6 Outfall 02/04/05	1,648	
Bag 7 Outfall 02/04/05	654	

TOTAL ESTIMATED PLASTICS: 20,858.57



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 2/12/2024

LOCATION: AOC 24

START Latitude/Longitude: 28.40.5128770, -96.32.0706843

END Latitude/Longitude: 28.40.4941389, -96.32.0745800

ESTIMATED LF SHORELINE: 215

LOCATION: AOC 25

START Latitude/Longitude: 28.40.4902324, -96.32.0751569

END Latitude/Longitude: 28.40.4553791, -96.32.0991284

ESTIMATED LF SHORELINE: 413

LOCATION: AOC 43

START Latitude/Longitude: 28.40.5362583, -96.32.1315457

END Latitude/Longitude: 28.40.5512476, -96.32.1171118

ESTIMATED LF SHORELINE: 201

TOTAL BAGS COLLECTED BY ENTACT: 50 (10 at AOC 24, 36 at AOC 25, 4 at AOC 43)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/13/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 24	1,200	1,792
Bag 2 AOC 24	2,384	
Bag 1 AOC 25	1,096	1,362.29
Bag 2 AOC 25	632	
Bag 3 AOC 25	1,120	
Bag 4 AOC 25	976	
Bag 5 AOC 25	2,016	
Bag 6 AOC 25	1,376	
Bag 7 AOC 25	2,320	
Bag 1 AOC 43	1,872	1,872

TOTAL ESTIMATED PLASTICS: 74,450.29



DATE: 2/13/2024

Location: AOC 17

START Latitude/Longitude: 28.41.1997614, -96.31.4429963

END Latitude/Longitude: 28.41.2020858, -96.31.4446151

ESTIMATED LF SHORELINE: 28

Location: Outfall 06

START Latitude/Longitude: 28.41.2020903, -96.31.4456274

END Latitude/Longitude: 28.41.2060746, -96.31.4478350

ESTIMATED LF SHORELINE: 184

AOC 47 SE Turbidity Curtain

Outfall 08 Turbidity Curtain

Outfall 09 Turbidity Curtain

AOC 48 N Turbidity Curtain

AOC 40 N Turbidity Curtain

Outfall 02/04/05 Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 68 (1 at AOC 47 SE TBC; 2 at Outfall 08 TBC; 2 at Outfall 09 TBC; 2 at AOC 48 N TBC; 5 at Outfall 02/04/05 TBC; 1 at AOC 40 N TBC; 31 at AOC 17; 24 at Outfall 06)

TOTAL SAMPLES PROCESSED BY FNI: 17

DATE PROCESSED BY FNI: 2/14/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 47 SE TBC	20,000	20,000
Bag 1 Outfall 08 TBC	3,648	3,648
Bag 1 Outfall 09 TBC	1,056	1,056
Bag 1 AOC 48 N TBC	1,456	1,456
Bag 1 AOC 40 N TBC	104	104
Bag 1 Outfall 02/04/05 TBC	2,352	2,352
Bag 1 AOC 17	648	1,118.67
Bag 2 AOC 17	528	
Bag 3 AOC 17	336	
Bag 4 AOC 17	1,040	
Bag 5 AOC 17	1,552	
Bag 6 AOC 17	2,608	
Bag 1 Outfall 06	45	440.60
Bag 2 Outfall 06	416	
Bag 3 Outfall 06	688	
Bag 4 Outfall 06	174	
Bag 5 Outfall 06	880	

TOTAL ESTIMATED PLASTICS: 89,437.07



DATE: 2/14/2024

Location: AOC 17

START Latitude/Longitude: 28.41.2020858, -86.31.4446151

END Latitude/Longitude: 28.41.2422022, -96.31.4689011

ESTIMATED LF SHORELINE: 412

Location: Outfall 06

START Latitude/Longitude: 28.41.2020131, -96.31.4552367

END Latitude/Longitude: 28.41.2969746, -96.31.4478350

ESTIMATED LF SHORELINE: 78

Location: GEAR Flag #45 (Outfall 08)

START Latitude/Longitude: 28.41.4961121, -96.31.5352195

END Latitude/Longitude: 28.41.4947926, -96.31.5284115

ESTIMATED LF SHORELINE: 62

Location: GEAR Flag #46 (Outfall 08)

START Latitude/Longitude: 28.41.4968402, 96.31.5407001

END Latitude/Longitude: 28.41.4965530, -96.31.5369330

ESTIMATED LF SHORELINE: 34

Location: GEAR Flag #47 (Outfall 06)

START Latitude/Longitude: 28.41.2226662, -96.31.4573514

END Latitude/Longitude: 28.41.2239650, -96.31.4577675

ESTIMATED LF SHORELINE: 14

Location: GEAR Flag #48 (Outfall 09)

START Latitude/Longitude: 28.42.0039119, -96.31.5125546

END Latitude/Longitude: 28.42.0024858, -96.31.5108456

ESTIMATED LF SHORELINE: 21

Location: GEAR Flag #49 (Outfall 08)

START Latitude/Longitude: 28.41.4830277, -96.31.5136538

END Latitude/Longitude: 28.41.4833092, -96.31.5157816

ESTIMATED LF SHORELINE: 19



TOTAL BAGS COLLECTED BY ENTACT: 43 (28 bags at AOC 17; 4 bags at Outfall 06; 4 bags at GEAR Flag #45; 3 bags at GEAR Flag #46; 2 bags at GEAR Flag #47; 1 bag at GEAR Flag #48; 1 bag at GEAR flag #49)

TOTAL SAMPLES PROCESSED BY FNI: 12

DATE PROCESSED BY FNI: 2/15/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 17	184	250.67
Bag 2 AOC 17	280	
Bag 3 AOC 17	736	
Bag 4 AOC 17	96	
Bag 5 AOC 17	144	
Bag 6 AOC 17	64	
Bag 1 Outfall 06	320	320
Bag 1 GEAR Flag #45	1,000	1,000
Bag 1 GEAR Flag #46	864	864
Bag 1 GEAR Flag #47	456	456
Bag 1 GEAR Flag #48	368	368
Bag 1 GEAR Flag #49	224	224

TOTAL ESTIMATED PLASTICS: 16,394.67



DATE: 2/15/2024

Location: AOC 17N

START Latitude/Longitude: 28.41.2417541, -96.31.4684687

END Latitude/Longitude: 28.41.2765682, -96.31.4756719

ESTIMATED LF SHORELINE: 365

Location: GEAR Flag #50 (Outfall 09)

START Latitude/Longitude: 28.41.5853990, -96.31.5050330

END Latitude/Longitude: 28.41.5831251, -96.31.554414

ESTIMATED LF SHORELINE: 23

Location: GEAR Flag #51 (Outfall 09)

START Latitude/Longitude: 28.42.0091375, -96.31.5132220

END Latitude/Longitude: 28.42.0058704, -96.31.5196390

ESTIMATED LF SHORELINE: 27

Location: GEAR Flag #52 (Outfall 08)

START Latitude/Longitude: 28.41.4904745, -96.31.5041614

END Latitude/Longitude: 28.41.4900072, -96.31.5064806

ESTIMATED LF SHORELINE: 21

Location: GEAR Flag #53 (Outfall 07)

START Latitude/Longitude: 28.41.3244062, -96.31.4350879

END Latitude/Longitude: 28.41.3218850, -96.31.4358634

ESTIMATED LF SHORELINE: 26

TOTAL BAGS COLLECTED BY ENTACT: 39 (31 bags at AOC 17N; 1 bag at GEAR Flag #50; 4 bags at GEAR Flag #51; 2 bags at GEAR Flag #52; 1 bag at GEAR Flag #53)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/19/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 17	89	133.17
Bag 2 AOC 17	163	
Bag 3 AOC 17	134	
Bag 4 AOC 17	73	
Bag 5 AOC 17	113	
Bag 6 AOC 17	227	
Bag 1 GEAR Flag #50	11	11
Bag 1 GEAR Flag #51	1,640	1,640
Bag 1 GEAR Flag #52	108	108
Bag 1 GEAR Flag #53	31	31

TOTAL ESTIMATED PLASTICS: 10,946.17



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 2/19/2024

LOCATION: AOC 14

START Latitude/Longitude: 28.41.2780811, -96.31.4755602

END Latitude/Longitude: 28.41.2965148, -96.31.4614523

ESTIMATED LF SHORELINE: 229

AOC 47 SE Turbidity Curtain

Outfall 02/04/05 Turbidity Curtain

SH-35 N Turbidity Curtain

AOC 40 N Turbidity Curtain

AOC 48 N Turbidity Curtain

Outfall 09 Turbidity Curtain

SH-35 S Turbidity Curtain

Outfall 08 Turbidity Curtain

Outfall 06 Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 48 (32 at AOC 14; 5 at AOC 47SE TBC; 3 at Outfall 02/04/05 TBC; 2 at SH-35N TBC; 1 at AOC 40 TBC; 1 at AOC 48 TBC; 1 at Outfall 09 TBC; 1 at SH-35S TBC; 1 at Outfall 08 TBC; 1 at Outfall 06 TBC)

TOTAL SAMPLES PROCESSED BY FNI: 16

DATE PROCESSED BY FNI: 2/20/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 14	64	77.86
Bag 2 AOC 14	26	
Bag 3 AOC 14	67	
Bag 4 AOC 14	52	
Bag 5 AOC 14	111	
Bag 6 AOC 14	127	
Bag 7 AOC 14	98	
Bag 1 AOC 47 SE TBC	2,352	2,352
Bag 1 Outfall 02/04/05 TBC	288	288
Bag 1 SH-35N TBC	3,440	3,440
Bag 1 AOC 40 TBC	80	80
Bag 1 AOC 48 TBC	272	272
Bag 1 Outfall 09 TBC	1,136	1,136
Bag 1 SH-35 S TBC	1,304	1,304
Bag 1 Outfall 08 TBC	1,216	1,216
Bag 1 Outfall 06 TBC	1,720	1,720

TOTAL ESTIMATED PLASTICS: 27,723.43



DATE: 2/20/2024

Location: AOC 14

START Latitude/Longitude: 28.41.2981051, -96.31.4600132
END Latitude/Longitude: 28.41.3289482, -96.31.4335665

ESTIMATED LF SHORELINE: 399

Location: AOC 12

START Latitude/Longitude: 28.41.3291445, -96.31.4334935
END Latitude/Longitude: 28.41.3576787, -96.31.4188583

ESTIMATED LF SHORELINE: 319

Location: AOC 10

START Latitude/Longitude: 28.41.3579947, -96.31.4188040
END Latitude/Longitude: 28.41.3692697, -96.31.4193394

ESTIMATED LF SHORELINE: 114

TOTAL BAGS COLLECTED BY ENTACT: 22 (16 at AOC 14; 5 at AOC 12; 1 at AOC 10)

TOTAL SAMPLES PROCESSED BY FNI: 6

DATE PROCESSED BY FNI: 2/21/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 14	336	752
Bag 2 AOC 14	288	
Bag 3 AOC 14	760	
Bag 4 AOC 14	1,624	
Bag 1 AOC 12	456	456
Bag 1 AOC 10	288	288

TOTAL ESTIMATED PLASTICS: 14,600



DATE: 2/21/2024

Location: AOC 17 N

START Latitude/Longitude: 28.41.1997308, -96.31.4430566
END Latitude/Longitude: 28.41.2018875, -96.31.4443096

ESTIMATED LF SHORELINE: 24

Location: Outfall 06

START Latitude/Longitude: 28.41.2021301, -96.31.4450564
END Latitude/Longitude: 28.41.2016372, -96.31.4550601

ESTIMATED LF SHORELINE: 109

Location: GEAR Flag #54 (Outfall 06)

START Latitude/Longitude: 28.41.2135469, -96.31.4576258
END Latitude/Longitude: 28.41.2122145, -96.31.4575339

ESTIMATED LF SHORELINE: 13

Location: AOC 09

START Latitude/Longitude: 28.41.3926292, -96.31.4191307
END Latitude/Longitude: 28.41.4063401, -96.31.4246933

ESTIMATED LF SHORELINE: 152

Location: AOC 10

START Latitude/Longitude: 28.41.3696178, -96.31.4195726
END Latitude/Longitude: 28.41.3921015, -96.31.4190588

ESTIMATED LF SHORELINE: 229

TOTAL BAGS COLLECTED BY ENTACT: 39 (15 bags at AOC 17 N; 20 bags at Outfall 06; 1 bag at GEAR Flag #54; 2 bags at AOC 09; 1 bag at AOC 10)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/22/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 17	992	1,293.33
Bag 2 AOC 17	1,264	
Bag 3 AOC 17	1,624	
Bag 1 Outfall 06	148	995
Bag 1 Outfall 06	312	
Bag 2 Outfall 06	216	
Bag 3 Outfall 06	3,304	
Bag 1 GEAR Flag #54 (Outfall 06)	32	32
Bag 1 AOC 09	296	296
Bag 1 AOC 10	208	208

TOTAL ESTIMATED PLASTICS: 40,132



DATE: 2/22/2024

Location: AOC 20

START Latitude/Longitude: 28.41.1781128, -96.31.4257139
END Latitude/Longitude: 28.41.1747185, -96.31.4213687

ESTIMATED LF SHORELINE: 52

Location: GEAR Flag #55 (Outfall 08)

START Latitude/Longitude: 28.41.4882034, -96.31.5132081
END Latitude/Longitude: 28.41.4895684, -96.31.5072326

ESTIMATED LF SHORELINE: 62

Location: AOC 14

START Latitude/Longitude: 28.41.2966414, -96.31.4612437
END Latitude/Longitude: 28.41.3015406, -96.31.4569440

ESTIMATED LF SHORELINE: 63

Location: AOC 09

START Latitude/Longitude: 28.41.4063401, -96.31.426933
END Latitude/Longitude: 28.41.4145343, -96.31.4309896

ESTIMATED LF SHORELINE: 100

Location: AOC 08

START Latitude/Longitude: 28.41.4147390, -96.31.4317303
END Latitude/Longitude: 28.41.4236920, -96.31.4383109

ESTIMATED LF SHORELINE: 108

TOTAL BAGS COLLECTED BY ENTACT: 26 (4 bags at AOC 20; 8 bags at GEAR Flag #55; 2 bags at AOC 14; 5 bags at AOC 09; 7 bags at AOC 08)

TOTAL SAMPLES PROCESSED BY FNI: 7

DATE PROCESSED BY FNI: 2/23/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 20	496	496
Bag 1 GEAR Flag #55 (Outfall 08)	328	412
Bag 2 GEAR Flag #55 (Outfall 08)	496	
Bag 1 AOC 14	624	624
Bag 1 AOC 09	344	344
Bag 1 AOC 08	216	244
Bag 2 AOC 08	272	

TOTAL ESTIMATED PLASTICS: 9,956



DATE: 2/23/2024

Location: Outfall 08

START Latitude/Longitude: 28.41.4901218, -96.31.5042157
END Latitude/Longitude: 28.41.4836338, -96.31.5109704

ESTIMATED LF SHORELINE: 141

Location: AOC 04

START Latitude/Longitude: 28.41.4932225, -96.31.5142127
END Latitude/Longitude: 28.41.4939947, -96.31.5245979

ESTIMATED LF SHORELINE: 93

Location: GEAR Flag #56 (Outfall 08)

START Latitude/Longitude: 28.41.4911683, -96.31.5411457
END Latitude/Longitude: 28.41.4917375, -96.31.5435675

ESTIMATED LF SHORELINE: 22

Location: AOC 08

START Latitude/Longitude: 28.41.4236865, -96.31.4383343
END Latitude/Longitude: 28.41.4392595, -96.31.4561820

ESTIMATED LF SHORELINE: 237

TOTAL BAGS COLLECTED BY ENTACT: 77 (25 bags at Outfall 08; 7 bags at AOC 04; 2 bags at GEAR Flag #56; 43 bags at AOC 08)

TOTAL SAMPLES PROCESSED BY FNI: 17

DATE PROCESSED BY FNI: 2/26/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 08	632	328
Bag 2 AOC 08	448	
Bag 3 AOC 08	232	
Bag 4 AOC 08	256	
Bag 5 AOC 08	264	
Bag 6 AOC 08	296	
Bag 7 AOC 08	328	
Bag 8 AOC 08	216	
Bag 9 AOC 08	280	
Bag 1 GEAR Flag #56 (Outfall 08)	1,712	1,712
Bag 1 Outfall 08	1,064	1,147.2
Bag 2 Outfall 08	1,392	
Bag 3 Outfall 08	1,032	
Bag 4 Outfall 08	1,104	
Bag 5 Outfall 08	1,144	
Bag 1 AOC 04	456	484
Bag 2 AOC 04	512	

TOTAL ESTIMATED PLASTICS: 64,341.6

Commented [LV1]: Data book says these are from AOC 05, but Entact report and gps coordinates are AOC 04.

Commented [JR2R1]: It AOC 04. My mistake in writing AOC 05.



Formosa Plastics Surface Cleaning Weekly Summary

(Monday– Friday)

DATE: 2/26/2024

LOCATION: AOC 08

START Latitude/Longitude: 28.41.4393469, -96.31.4568689

END Latitude/Longitude: 28.41.4394591, -96.31.4848672

ESTIMATED LF SHORELINE: 249

AOC 47 SE Turbidity Curtain

Outfall 02/04/05 Turbidity Curtain

SH-35 S Turbidity Curtain

AOC 40 N Turbidity Curtain

AOC 48 N Turbidity Curtain

Outfall 08 Turbidity Curtain

Outfall 06 Turbidity Curtain

TOTAL BAGS COLLECTED BY ENTACT: 50 (31 at AOC 08; 8 at AOC 47SE TBC; 5 at AOC 48 TBC; 2 at Outfall 02/04/05 TBC; 1 at SH-35S TBC; 1 at AOC 40 TBC; 1 at Outfall 08 TBC; 1 at Outfall 06 TBC)

TOTAL SAMPLES PROCESSED BY FNI: 15

DATE PROCESSED BY FNI: 2/27/2024



SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 08	168	667.43
Bag 2 AOC 08	448	
Bag 3 AOC 08	1,248	
Bag 4 AOC 08	560	
Bag 5 AOC 08	896	
Bag 6 AOC 08	808	
Bag 7 AOC 08	544	
Bag 1 AOC 47 SE TBC	17,960	16,444
Bag 2 AOC 47 SE TBC	14,928	
Bag 1 Outfall 02/04/05 TBC	1,192	1,192
Bag 1 AOC 40 TBC	496	496
Bag 1 AOC 48 TBC	584	584
Bag 1 SH-35S TBC	4,160	4,160
Bag 1 Outfall 08 TBC	3,416	3,416
Bag 1 Outfall 06 TBC	834	834

TOTAL ESTIMATED PLASTICS: 166,452.29



DATE: 2/27/2024

Location: AOC 08

START Latitude/Longitude: 28.41.441268, -96.31.4864904

END Latitude/Longitude: 28.41.4807194, -96.31.4979521

ESTIMATED LF SHORELINE: 432

Location: Outfall 08

START Latitude/Longitude: 28.41.4823001, -96.31.5007548

END Latitude/Longitude: 28.41.4890354, -96.31.5133743

ESTIMATED LF SHORELINE: 152

TOTAL BAGS COLLECTED BY ENTACT: 61 (50 at AOC 08; 11 at Outfall 08)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 2/28/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 08	448	1,095.2
Bag 2 AOC 08	144	
Bag 3 AOC 08	752	
Bag 4 AOC 08	2,496	
Bag 5 AOC 08	1,872	
Bag 6 AOC 08	424	
Bag 7 AOC 08	1,240	
Bag 8 AOC 08	1,824	
Bag 9 AOC 08	328	
Bag 10 AOC 08	1,424	
Bag 1 Outfall 08	768	685.33
Bag 2 Outfall 08	456	
Bag 3 Outfall 08	832	

TOTAL ESTIMATED PLASTICS: 62,298.67



DATE: 2/28/2024

Location: GEAR Flag #57 (Outfall 06)

START Latitude/Longitude: 28.41.2021981, -96.31.4452658

END Latitude/Longitude: 28.41.2016562, -96.31.4471724

ESTIMATED LF SHORELINE: 18

Location: GEAR Flag #58 (Outfall 07)

START Latitude/Longitude: 28.41.3156591, -96.31.4410465

END Latitude/Longitude: 28.41.3146646, -96.31.4424175

ESTIMATED LF SHORELINE: 16

Location: AOC 04

START Latitude/Longitude: 28.41.4932433, -96.31.5079262

END Latitude/Longitude: 28.41.5216700, -96.31.5418982

ESTIMATED LF SHORELINE: 584

TOTAL BAGS COLLECTED BY ENTACT: 46 (40 bags at AOC 04; 4 bags at GEAR Flag #58; 2 bags at GEAR Flag #57)

TOTAL SAMPLES PROCESSED BY FNI: 10

DATE PROCESSED BY FNI: 2/29/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 04	1,064	923
Bag 2 AOC 04	1,016	
Bag 3 AOC 04	1,928	
Bag 4 AOC 04	1,216	
Bag 5 AOC 04	376	
Bag 6 AOC 04	392	
Bag 7 AOC 04	416	
Bag 8 AOC 04	976	
Bag 1 GEAR Flag #57 (Outfall 06)	2,224	2,224
Bag 1 GEAR Flag #58 (Outfall 07)	496	496

TOTAL ESTIMATED PLASTICS: 43,352



DATE: 2/29/2024

Location: AOC 04

START Latitude/Longitude: 28.41.5219851, -96.31.5419533

END Latitude/Longitude: 28.41.5545295, -96.31.5373510

ESTIMATED LF SHORELINE: 370

Location: AOC 23

START Latitude/Longitude: 28.40.5720906, -96.32.0874202

END Latitude/Longitude: 28.40.5771181, -96.32.0938744

ESTIMATED LF SHORELINE: 77

Location: AOC 43

START Latitude/Longitude: 28.40.5526118, -96.32.1162813

END Latitude/Longitude: 28.40.5431774, -96.32.1228772

ESTIMATED LF SHORELINE: 112

TOTAL BAGS COLLECTED BY ENTACT: 55 (36 bags at AOC 04; 9 bags at Outfall 02/04/05; 8 bags at AOC 43; 2 bags at AOC 23)

TOTAL SAMPLES PROCESSED BY FNI: 13

DATE PROCESSED BY FNI: 3/1/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 04	4,376	2,760
Bag 2 AOC 04	1,264	
Bag 3 AOC 04	232	
Bag 4 AOC 04	1,296	
Bag 5 AOC 04	13,784	
Bag 6 AOC 04	424	
Bag 7 AOC 04	168	
Bag 8 AOC 04	536	
Bag 1 AOC 43	1,624	1,488
Bag 2 AOC 43	1,352	
Bag 1 Outfall 02/04/05	376	964
Bag 2 Outfall 02/04/05	1,552	
Bag 1 AOC 23	1,344	1,344

TOTAL ESTIMATED PLASTICS: 122,628



DATE: 3/1/2024

Location: Outfall 06

START Latitude/Longitude: 28.41.2020541, -96.31.4458955

END Latitude/Longitude: 28.41.2000915, -96.31.4517165

ESTIMATED LF SHORELINE: 56

Location: AOC 04

START Latitude/Longitude: 28.41.5545295, -96.31.5373510

END Latitude/Longitude: 28.41.5678999, -96.31.5225990

ESTIMATED LF SHORELINE: 188

Location: AOC 17

START Latitude/Longitude: 28.41.1998167, -96.31.4430151

END Latitude/Longitude: 28.41.2021247, -96.31.4447831

ESTIMATED LF SHORELINE: 28

TOTAL BAGS COLLECTED BY ENTACT: 41 (19 bags at AOC 04; 19 bags at Outfall 06; 3 bags at AOC 17)

TOTAL SAMPLES PROCESSED BY FNI: 9

DATE PROCESSED BY FNI: 3/1/2024

SAMPLES PROCESSED:

SAMPLE #	ESTIMATED NUMBER PLASTICS	AVERAGE NUMBER OF PLASTICS PER BAG
Bag 1 AOC 04	1,536	1,060
Bag 2 AOC 04	1,016	
Bag 3 AOC 04	744	
Bag 4 AOC 04	944	
Bag 1 Outfall 06	3,816	2,444
Bag 2 Outfall 06	1,936	
Bag 3 Outfall 06	1,568	
Bag 4 Outfall 06	2,456	
Bag 1 AOC 17	1,080	1,080

TOTAL ESTIMATED PLASTICS: 69,816