

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:55am	End Time: 8:09am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463018 -96.416091		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463219 -96.416330		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/8/26	BRA #: 150-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 11:22am	End Time: 11:30am	Duration: 8min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.476955 -96.433514		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA150-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/8/26	BRA #: 119-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:06am	End Time: 9:20am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.533470 -96.513507		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA119-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/8/26	BRA #: 118-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:43am	End Time: 9:55am	Duration: 12min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.537448 -96.515143		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA118-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/9/26	BRA #: 117-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:30am	End Time: 8:46am	Duration: 16min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.541018 -96.516572		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☐ Other (describe below) ☐		
General Site Observations: Shell hash in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA117-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date:	BRA #:	Tide: LOW / NORMAL / HIGH	
Start Time:	End Time:	Duration:	
Field Supervisor:		# Crew Members:	
Latitude / Longitude (transect start):			
Weather (wind speed/direction, precipitation):			
Location Type: Sandy Beach / Shell Hash Beach / Vegetated Shoreline / Other (describe below)			
General Site Observations:			
Most Plastics Collected: YES / NO (if no, explain)			
Boom/Silt Fence Utilized: YES / NO		Plastics Type Present: PELLETS / POWDER / BOTH	
Quantitative Assessment:	Q1:	Q2:	Q3:
	Q4:	Q5:	Q6:
Qualitative Assessment:			
Cleanup Technique(s) Implemented¹:			
No. of Bags Collected:			
Bag Quality Control:	A:	B:	C:
	D:	E:	F:
Estimated Number Plastic Pellets Removed²:			
Estimated Volume Powder Removed³:			
Photo(s) Taken: YES / NO		Photo ID(s):	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample			

Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:55am	End Time: 8:09am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463018 -96.416091		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463219 -96.416330		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 4S-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:34am	End Time: 7:38am	Duration: 4min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.669312 -96.571076		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA4S-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 4S-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:38am	End Time: 7:44am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.669121 -96.571329		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA4S-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 4S-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:44am	End Time: 7:49am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668930 -96.571597		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA4S-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.668930
Longitude: -96.571597
Elevation: 2.58±5.04 m
Accuracy: 2.87 m
Time: 05-06-2026 07:44:07
Note: BRA4S-3

NoteCam (6/4/26)

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:55am	End Time: 8:09am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463018 -96.416091		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463219 -96.416330		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented ¹ : n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed ² : 0		
Estimated Volume Powder Removed ³ : 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation		
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample		
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 5S-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:49am	End Time: 7:54am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668696 -96.572864		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA5S-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 5S-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:54am	End Time: 7:59am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668639 -96.573144		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA5S-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 5S-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:59am	End Time: 8:04am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.668569 -96.573425		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA5S-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:55am	End Time: 8:09am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463018 -96.416091		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463219 -96.416330		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 6S-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:04am	End Time: 8:09am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666835 -96.576123		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA6S-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 6S-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666682 -96.576424		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA6S-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 6S-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:14am	End Time: 8:19am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.666533 -96.576707		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA6S-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:55am	End Time: 8:09am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463018 -96.416091		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐						
Start Time: 8:09am	End Time: 8:14am	Duration: 15min						
Field Supervisor: Erik		# Crew Members: 5						
Latitude / Longitude (transect start): 28.463219 -96.416330								
Weather (wind speed/direction, precipitation): 15mph NNW, 0%								
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐								
General Site Observations: Sandy beach and vegetation in area.								
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.								
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐								
Quantitative Assessment: <table border="0"> <tr> <td>Q1: 0</td> <td>Q2: 0</td> <td>Q3: 0</td> </tr> <tr> <td>Q4: 0</td> <td>Q5: 0</td> <td>Q6: 0</td> </tr> </table>			Q1: 0	Q2: 0	Q3: 0	Q4: 0	Q5: 0	Q6: 0
Q1: 0	Q2: 0	Q3: 0						
Q4: 0	Q5: 0	Q6: 0						
Qualitative Assessment: No plastics found during qualitative assessments.								
Cleanup Technique(s) Implemented ¹ : n/a								
No. of Bags Collected: 0								
Bag Quality Control: <table border="0"> <tr> <td>A: 0</td> <td>B: 0</td> <td>C: 0</td> </tr> <tr> <td>D: 0</td> <td>E: 0</td> <td>F: 0</td> </tr> </table>			A: 0	B: 0	C: 0	D: 0	E: 0	F: 0
A: 0	B: 0	C: 0						
D: 0	E: 0	F: 0						
Estimated Number Plastic Pellets Removed ² : 0								
Estimated Volume Powder Removed ³ : 0								
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA155-3						
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation								
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample								
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample								



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 7S-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:19am	End Time: 8:24am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664435 -96.579857		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA7S-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 7S-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:24am	End Time: 8:29am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664231 -96.580103		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA7S-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 7S-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:29am	End Time: 8:40am	Duration: 11min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.664033 -96.580334		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA7S-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:41am	End Time: 7:55am	Duration: 14min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.462357 -96.416243		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26		BRA #: 155-2		Tide: LOW ☐ NORMAL ☒ HIGH ☐	
Start Time: 7:55am		End Time: 8:09am		Duration: 14min	
Field Supervisor: Erik				# Crew Members: 5	
Latitude / Longitude (transect start): 28.463018 -96.416091					
Weather (wind speed/direction, precipitation): 15mph NNW, 0%					
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐					
General Site Observations: Sandy beach and vegetation in area.					
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.					
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐					
Quantitative Assessment:		Q1: 0	Q2: 0	Q3: 0	
		Q4: 0	Q5: 0	Q6: 0	
Qualitative Assessment: No plastics found during qualitative assessments.					
Cleanup Technique(s) Implemented ¹ : n/a					
No. of Bags Collected: 0					
Bag Quality Control:		A: 0	B: 0	C: 0	
		D: 0	E: 0	F: 0	
Estimated Number Plastic Pellets Removed ² : 0					
Estimated Volume Powder Removed ³ : 0					
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA155-2			
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample					



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 4/7/26	BRA #: 155-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:09am	End Time: 8:14am	Duration: 15min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.463219 -96.416330		
Weather (wind speed/direction, precipitation): 15mph NNW, 0%		
Location Type: Sandy Beach ☒ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Sandy beach and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA155-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 8S-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:40am	End Time: 8:45am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.662046 -96.582510		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8S-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 8S-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:45am	End Time: 8:50am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661869 -96.582748		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8S-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/6/26	BRA #: 8S-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:50am	End Time: 8:55am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.661662 -96.582997		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA8S-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 33-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 14:07pm	End Time: 14:12pm	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.636560 -96.570573		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA33-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 33-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 14:12pm	End Time: 14:16pm	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.637126 -96.570296		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA33-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26		BRA #: 33-3		Tide: LOW ☐ NORMAL ☒ HIGH ☐	
Start Time: 14:16pm		End Time: 14:21pm		Duration: 5min	
Field Supervisor: Erik				# Crew Members: 5	
Latitude / Longitude (transect start): 28.637705 -96.570182					
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%					
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒					
General Site Observations: 1a dirt and vegetation in area.					
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.					
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐					
Quantitative Assessment:		Q1: 0	Q2: 0	Q3: 0	
		Q4: 0	Q5: 0	Q6: 0	
Qualitative Assessment: No Plastics found during qualitative assessments.					
Cleanup Technique(s) Implemented ¹ : n/a					
No. of Bags Collected: 0					
Bag Quality Control:		A: 0	B: 0	C: 0	
		D: 0	E: 0	F: 0	
Estimated Number Plastic Pellets Removed ² : 0					
Estimated Volume Powder Removed ³ : 0					
Photo(s) Taken: YES ☒ NO ☐		Photo ID(s): BRA33-3			
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample					



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26		BRA #: 34-1		Tide: LOW ☐ NORMAL ☒ HIGH ☐	
Start Time: 13:43pm		End Time: 13:47pm		Duration: 5min	
Field Supervisor: Erik				# Crew Members: 5	
Latitude / Longitude (transect start): 28.640204 -96.572323					
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%					
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒					
General Site Observations: 1a dirt and vegetation in area.					
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.					
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐					
Quantitative Assessment:		Q1: 0	Q2: 0	Q3: 0	
		Q4: 0	Q5: 0	Q6: 0	
Qualitative Assessment: No Plastics found during qualitative assessments.					
Cleanup Technique(s) Implemented ¹ : n/a					
No. of Bags Collected: 0					
Bag Quality Control:		A: 0	B: 0	C: 0	
		D: 0	E: 0	F: 0	
Estimated Number Plastic Pellets Removed ² : 0					
Estimated Volume Powder Removed ³ : 0					
Photo(s) Taken: YES ☒ NO ☐			Photo ID(s): BRA34-1		
¹ Cleanup Technique Descriptions: - Type 1: Low-pressure washing of shoreline - Type 2: Netting plastics from waters surface - Type 3: Hand-picking plastics from shoreline or other surface - Type 4: Vacuum - Type 5: Total wrack removal - Type 6: Plastics removal with wrack separation					
² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample					
³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample					



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 34-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 13:47pm	End Time: 13:51pm	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.640674 -96.572415		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA34-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 34-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 13:51pm	End Time: 14:07pm	Duration: 16min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.641092 -96.572531		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA34-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 35-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 13:10pm	End Time: 13:17pm	Duration: 7
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.644186 -96.574498		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 35-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 13:17pm	End Time: 13:22pm	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.643711 -96.574109		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/13/26	BRA #: 35-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 13:22pm	End Time: 13:43pm	Duration: 22min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.643711 -96.574109		
Weather (wind speed/direction, precipitation): 13mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA35-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 81-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:12am	End Time: 8:18am	Duration: 7min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.594670 -96.613022		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA81-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 81-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:18am	End Time: 8:25am	Duration: 7min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.594943 -96.613063		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA81-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 81-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:25am	End Time: 8:30am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.595574 -96.612369		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA81-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 83-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:46am	End Time: 7:53am	Duration: 7min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.591528 -96.614340		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 83-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:53am	End Time: 7:59am	Duration: 7min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592092 -96.614570		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q3: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		C: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		




Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 5/14/26	BRA #: 83-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 7:59am	End Time: 8:12am	Duration: 13min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.592616 -96.614376		
Weather (wind speed/direction, precipitation): 10mph, SSW, 0%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☐ Vegetated Shoreline ☒ Other (describe below) ☒		
General Site Observations: la dirt and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No Plastics found.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No Plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA83-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 26-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:31am	End Time: 9:36am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.626059 -96.560919		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 26-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 26-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:36am	End Time: 9:41am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.626276 -96.560728		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 26-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 26-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 9:41am	End Time: 9:47am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.626597 -96.560528		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 26-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 31-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:27am	End Time: 8:32am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.645768 -96.568380		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 31-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 31-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:32am	End Time: 8:37am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.645451 -96.568416		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 31-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Latitude: 28.645451
Longitude: -96.568416
Elevation: 1.81±5.27 m
Accuracy: 3.36 m
Time: 06-03-2026 08:32:17
Note: Bra 31-2

06-03-2026 08:32

Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 31-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:37am	End Time: 8:46am	Duration: 10min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.645190 -96.568524		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 31-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 32-1	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:46am	End Time: 8:52am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.642699 -96.569122		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 32-1	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 32-2	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:52am	End Time: 8:57am	Duration: 6min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.642460 -96.569305		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): 32-2	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.

Bay Plastics Daily Cleanup Activity Form for Formosa Plastics Remediation Project

Date: 6/3/26	BRA #: 32-3	Tide: LOW ☐ NORMAL ☒ HIGH ☐
Start Time: 8:57am	End Time: 9:31am	Duration: 5min
Field Supervisor: Erik		# Crew Members: 5
Latitude / Longitude (transect start): 28.641421 -96.569555		
Weather (wind speed/direction, precipitation): 5mph, SSW, 40%		
Location Type: Sandy Beach ☐ Shell Hash Beach ☒ Vegetated Shoreline ☒ Other (describe below) ☐		
General Site Observations: Shell hash and vegetation in area.		
Most Plastics Collected: YES ☐ NO (if no, explain) ☒ No plastics found in area.		
Boom/Silt Fence Utilized: YES ☐ NO ☒ Plastics Type Present: PELLETS ☐ POWDER ☐ BOTH ☐		
Quantitative Assessment:	Q1: 0	Q2: 0
	Q4: 0	Q5: 0
		Q6: 0
Qualitative Assessment: No plastics found during qualitative assessments.		
Cleanup Technique(s) Implemented¹: n/a		
No. of Bags Collected: 0		
Bag Quality Control:	A: 0	B: 0
	D: 0	E: 0
		F: 0
Estimated Number Plastic Pellets Removed²: 0		
Estimated Volume Powder Removed³: 0		
Photo(s) Taken: YES ☒ NO ☐	Photo ID(s): BRA 32-3	
¹ Cleanup Technique Descriptions: Type 1: Low-pressure washing of shoreline Type 2: Netting plastics from waters surface Type 3: Hand-picking plastics from shoreline or other surface Type 4: Vacuum Type 5: Total wrack removal Type 6: Plastics removal with wrack separation ² Methodology for weight/volume of plastic pellets removed: 1 - Total count 2 - Volumetric subsample ³ Methodology for volume powder removed: 1 - Total volume removed 2 - Volumetric subsample		



Shoreline BEFORE interim bay cleanup activities.

No after photo was taken due to no pellets found within the BRA.

Shoreline AFTER interim bay cleanup activities.